



Instruction Manual  
**optoNCDT 1700**  
**optoNCDT 1710**

ILD1700-2  
ILD1700-10  
ILD1700-20  
ILD1700-40  
ILD1700-50  
ILD1700-100

ILD1700-200  
ILD1700-250VT  
ILD1700-500  
ILD1700-750

ILD1700-2DR  
ILD1700-10DR  
ILD1700-20DR

ILD1700-2LL  
ILD1700-10LL  
ILD1700-20LL  
ILD1700-50LL

ILD1710-50  
ILD1710-1000

ILD1700-20BL  
ILD1700-200BL  
ILD1700-500BL  
ILD1700-750BL  
ILD1710-50BL  
ILD1710-1000BL

Intelligent laser optical displacement measurement

MICRO-EPSILON  
MESSTECHNIK  
GmbH & Co. KG  
Königbacher Strasse 15

94496 Ortenburg / Germany

Tel. +49 (0) 8542 / 168-0  
Fax +49 (0) 8542 / 168-90  
e-mail [info@micro-epsilon.de](mailto:info@micro-epsilon.de)  
[www.micro-epsilon.com](http://www.micro-epsilon.com)



Certified acc. to DIN EN ISO 9001: 2008

Softwareversion: 6.000

---

# Contents

<b>1.</b>	<b>Safety .....</b>	<b>7</b>
1.1	Symbols Used .....	7
1.2	Warnings .....	7
1.3	Notes on CE Identification .....	8
1.4	Proper Use .....	9
1.5	Proper Environment .....	9
<b>2.</b>	<b>Laser class .....</b>	<b>10</b>
<b>3.</b>	<b>Functional Principle, Technical Data .....</b>	<b>12</b>
3.1	Functional Principle .....	12
3.1.1	Diffuse Reflection .....	12
3.1.2	Direct Reflection .....	13
3.2	Real Time Control .....	13
3.3	Exposure Control .....	14
3.4	Technical Data .....	14
3.5	Control and Indicator Elements .....	19
<b>4.</b>	<b>Delivery .....</b>	<b>20</b>
4.1	Scope of Delivery .....	20
4.2	Storage .....	20
<b>5.</b>	<b>Installation .....</b>	<b>20</b>
5.1	Sensor Mounting Diffuse Reflection .....	20
5.2	Sensor Mounting Direct Reflection .....	27
5.3	Connector and Sensor Cable .....	30
5.4	Switching Inputs Laser On/Off, Setting Masters and the Mid-point .....	31
<b>6.</b>	<b>Operation .....</b>	<b>32</b>
6.1	Getting Ready for Operation .....	32
6.2	Membrane Keys .....	33
6.3	LED-Functions .....	34
6.4	Inputs and Outputs .....	34
6.5	Menue, Setting the Parameters .....	35

6.6	Average Setting .....	37
6.6.1	Averaging Number N.....	37
6.6.2	Moving Average (Default Setting) .....	38
6.6.3	Recursive Average.....	39
6.6.4	Median .....	39
6.7	Setting Masters .....	40
6.8	Setting Mid-Point .....	42
6.9	Frequency and Output Rate .....	44
6.10	Operation Mode.....	45
6.10.1	Error Mode (Error Control).....	45
6.10.2	Switch Mode .....	45
6.10.3	Output Circuit for the Switching Outputs .....	47
6.11	Synchronization of Sensors.....	47
6.12	Exposure Time.....	48
6.13	Timing, Measurement Value Flux .....	49
6.14	Triggering.....	51
6.14.1	Basics .....	51
6.14.2	Trigger Modes.....	51
6.14.3	Trigger Signal Levels .....	52
6.14.4	Trigger Pulse.....	52
6.14.5	Pin Assignment for External Trigger Signal.....	53
<b>7.</b>	<b>Measurement Value Output .....</b>	<b>54</b>
7.1	Voltage Output.....	54
7.2	Current Output.....	55
7.3	Digital Value Output.....	55
7.4	Digital Error Modes.....	56
<b>8.</b>	<b>Serial Interface RS422 .....</b>	<b>57</b>
8.1	Interface Parameters.....	58
8.2	Data Format for Measurement Values and Error Codes.....	58
8.2.1	Binary Format .....	58
8.2.2	ASCII Format .....	59
8.3	Set-up of the Commands .....	60
8.4	Command Reply.....	61
8.4.1	Communication without Error .....	61
8.4.2	Communication with Error.....	62

8.5	Commands .....	63
8.5.1	Overview .....	63
8.5.2	Reading out the Sensor Parameters .....	65
8.5.3	Reading out the Sensor Settings .....	66
8.5.4	Set Average Number .....	70
8.5.5	Set Average Type.....	73
8.5.6	Starting and Stopping the Measurement Value Output.....	74
8.5.7	Set Limit Values .....	75
8.5.8	Assignment of the Limits to the Switch Outputs .....	76
8.5.9	Operation Mode.....	77
8.5.10	Set the Measurement Value Output Type .....	78
8.5.11	Set Measurement Frequency (Speed).....	78
8.5.12	Error Output (Analog Output).....	80
8.5.13	Synchronous and Trigger Mode .....	81
8.5.14	Switching off the Laser (External) .....	82
8.5.15	Switching the Data Format .....	83
8.5.16	Key Lock .....	84
8.5.17	Set Factory Setting .....	84
8.5.18	Reset Sensor .....	85
8.5.19	Reading out the Measurements .....	86
8.5.20	Enable / Lock the Flash for Setting Masters and the Mid-point .....	87
8.5.21	Mastering or Setting Mid-point.....	88
<b>9.</b>	<b>Instruction for Operating .....</b>	<b>90</b>
9.1	Reflection Factor of the Target Surface .....	90
9.2	Error Influences.....	91
9.2.1	Light from other Sources.....	91
9.2.2	Color Differences .....	91
9.2.3	Temperature Influences .....	91
9.2.4	Mechanical Vibration .....	91
9.2.5	Movement Blurs.....	91
9.2.6	Surface Roughness .....	92
9.2.7	Sensor Tilting.....	92
9.3	Optimizing the Measuring Accuracy .....	93
9.4	Protective Housing .....	94

---

<b>10.</b>	<b>ILD1700 Tool .....</b>	<b>97</b>
10.1	Installation and Preparation for Measurements .....	97
	10.1.1 System Requirements .....	97
	10.1.2 Cable and Program Routine Requirements .....	97
10.2	Measurement .....	98
<b>11.</b>	<b>Software Support with MEDAQLib .....</b>	<b>99</b>
<b>12.</b>	<b>Warranty.....</b>	<b>100</b>
<b>13.</b>	<b>Service, Repair .....</b>	<b>100</b>
<b>14.</b>	<b>Decommissioning, Disposal .....</b>	<b>100</b>
<b>15.</b>	<b>Appendix.....</b>	<b>101</b>
15.1	Output Rate optoNCDT1700 .....	101
15.2	Pin Assignment Sensor Cable.....	102
15.3	Pin Assignment RS422 Connection .....	103
15.4	Factory Setting.....	104
15.5	Pin Assignment PC1700-x/x/USB/OE/IND .....	104
15.6	Accessory .....	105

## 1. Safety

The handling of the sensor assumes knowledge of the instruction manual.

### 1.1 Symbols Used

The following symbols are used in this instruction manual:



WARNING! - potentially dangerous situation



IMPORTANT! - useful tips and information

### 1.2 Warnings

Avoid unnecessary laser radiation to be exposed to the human body

- Switch off the sensor for cleaning and maintenance.
- Switch off the sensor for system maintenance and repair if the sensor is integrated into a system.

Caution - use of controls or adjustments or performance of procedures other than those specified herein may result in hazardous radiation exposure.

Connect the power supply and the display/output device in accordance with the safety regulations for electrical equipment.

- > Danger of injury
- > Damage to or destruction of the sensor

Avoid banging and knocking the sensor.

- > Damage to or destruction of the sensor

The power supply may not exceed the specified limits

- > Damage to or destruction of the sensor

Avoid continuous exposure to spray on the sensor.

> Damage to or destruction of the sensor

Avoid exposure to aggressive materials (washing agent, penetrating liquids or similar) on the sensor.

> Damage to or destruction of the sensor

### **1.3 Notes on CE Identification**

The following applies to the optoNCDT1700:

- EU directive 2004/108/EC
- EU directive 2011/65/EC, "RoHS" category 9

Products which carry the CE mark satisfy the requirements of the quoted EU directives and the European standards (EN) listed therein. The EC declaration of conformity is kept available according to EC regulation, article 10 by the authorities responsible at

MICRO-OPTRONIC MESSTECHNIK GmbH  
Lessingstraße 14  
01465 Langebrück / Germany

The sensor is designed for use in industry and to satisfy the requirements of the standards

- EN 61326-1: 2006-10  
Electrical equipment for measurement, control and laboratory use - EMC requirements - Part 1: General requirements
- DIN EN 55011: 2007-11 (Group 1, class B)  
Industrial, scientific and medical (ISM) radio-frequency equipment - Electromagnetic disturbance characteristics - Limits and methods of measurement
- EN 61000-6-2: 2006-03  
Electromagnetic compatibility (EMC), Part 6-2: Generic standards, Immunity for industrial environments

The sensor satisfies the requirements if they comply with the regulations described in the operating manual for installation and operation.

## 1.4 Proper Use

- The optoNCDT1700 is designed for use in industrial areas. It is used
  - for measuring displacement, distance, position and elongation
  - for in-process quality control and dimensional testing
- The sensor may only be operated within the limits specified in the technical data, see Chap. 3.4.
- The sensor should only be used in such a way that in case of malfunctions or failure personnel or machinery are not endangered.
- Additional precautions for safety and damage prevention must be taken for safety-related applications.

## 1.5 Proper Environment

- Protection class: IP 65 (Only with sensor cable connected )
- Lenses are excluded from protection class. Contamination of the lenses leads to impairment or failure of the function.
- Operating temperature: 0 to +50 °C (+32 to +104 °F)
- Storage temperature: -20 to +70 °C (-4 to +158 °F)
- Humidity: 5 - 95 % (no condensation)
- Pressure: atmospheric pressure
- EMC: according to:
  - EN 61326-1: 2006-10  
Electrical equipment for measurement, control and laboratory use - EMC requirements - Part 1: General requirements
  - DIN EN 55011: 2007-11 (Group 1, class B)  
Industrial, scientific and medical (ISM) radio-frequency equipment - Electromagnetic disturbance characteristics - Limits and methods of measurement
  - EN 61000-6-2: 2006-03  
Electromagnetic compatibility (EMC), Part 6-2: Generic standards, Immunity for industrial environments



### IMPORTANT!

The protection class is limited to water (no penetrating liquids or similar)!

## 2. Laser class

### **i** IMPORTANT!

Comply with all regulations on lasers.

The optoNCDT1700 sensors operate with a semiconductor laser with a wavelength of 670 nm (visible/red, ILD 1700) respectively 405 nm (visible/blue, ILD 1700BL). The laser is operated on a pulsed mode, the pulse frequency corresponding to the measuring frequency. The duration of the pulse is regulated in dependency on the object to be measured and can form an almost permanent beam. The maximum optical power is  $\leq 1$  mW. The sensors fall within Laser Class 2 (II).

Class 2 (II) lasers are not notifiable and a laser protection officer is not required either.

The following warning labels are attached to the cover (front and/or rear side) of the sensor housing:

### **!** WARNING!

Never deliberately look into the laser beam! Consciously close your eyes or turn away immediately if ever the laser beam should hit your eyes.



IEC label



Only for USA



IEC label for ILD1700-x BL only

During operation of the sensor the pertinent regulations acc. to EN 60825-1 on „radiation safety of laser equipment“ must be fully observed at all times. The sensor complies with all applicable laws for the manufacturer of laser devices.

### **i** IMPORTANT!

If both warning labels are covered over when the unit is installed the user must ensure that supplementary labels are applied.





Fig. 1 True reproduction of the sensor with its actual location of the warning labels, ILD1700-x

The laser warning labels for Germany have already been applied. Those for other non German-speaking countries an IEC standard label is included in delivery. The versions applicable to the user's country must be applied before the equipment is used for the first time. Laser operation is indicated by LED, see Chap. 3.5.

Although the laser output is low looking directly into the laser beam must be avoided. Due to the visible light beam eye protection is ensured by the natural blink reflex.

The housing of the optical sensors optoNCDT 1700 may only be opened by the manufacturer, see Chap. 12.. For repair and service purposes the sensors must always be sent to the manufacturer.




Fig. 2 True reproduction of the sensor with its actual location of the warning labels, ILD1710-1000

### 3. Functional Principle, Technical Data

#### 3.1 Functional Principle

##### 3.1.1 Diffuse Reflection

SMR = Start of measuring range

MMR = Midrange

EMR = End of measuring range

The optoNCDT1700 consists of a laser-optical sensor and a signal conditioning electronics. The sensor uses the principle of optical triangulation, i.e. a visible, modulated point of light is projected onto the target surface.

The diffuse element of the reflection of the light spot is imaged by a receiver optical element positioned at a certain angle to the optical axis of the laser beam onto a high-sensitivity resolution element (CCD), in dependency on distance. From the output signal of the CCD element a digital signal processor (DSP) in the sensor calculates the distance between the light spot on the object being measured and the sensor. The distance is linearized and then issued via an analog or digital interface.




Fig. 3 Definition of terms, output signal

### 3.1.2 Direct Reflection

The optoNCDT1700DR consists of an laser-optical sensor and a signal conditioning electronics. The sensor uses the principle of optical triangulation, i.e. a visible, modulated point of light is projected onto the target surface. The direct element of the reflection of the light spot is imaged by a receiver optical element onto a high-sensitivity resolution element (CCD), in dependency on distance. From the output signal of the CCD element a digital signal processor (DSP) in the sensor calculates the distance between the light spot on the object being measured and the sensor. The distance is linearized and then issued via an analog or digital interface.

On shining or mirroring surfaces the direct element of the reflection of the laser spot is greater and covers therefore the diffuse part. Suppression of the 2<sup>nd</sup> reflection from the glass rear side in the sensor is possible for measurements on glass panels. Sensors for direct reflection (ILD1700-2DR, ILD1700-10DR and ILD1700-20DR) are calibrated in tilted position. Therefore the can not be used for diffuse reflection.

SMR = Start of measuring range

MMR = Midrange

EMR = End of measuring range




Fig. 4 Definiton of terms, output signal

### 3.2 Real Time Control

The signal from the CCD element is used to determine the intensity of the diffuse reflection. This enables the sensor to compensate for fluctuations in brightness on the object being measured. What is more, it does so in a range from almost total absorption to almost total reflection.

### 3.3 Exposure Control

Dark or shining objects to be measured may require a longer exposure time. However, the controller is not capable of providing exposure which is any longer than permitted by the measurement frequency. For a longer exposure time, therefore, the measurement frequency of the sensor has to be reduced either manually or by command, see Chap. 6.9.

### 3.4 Technical Data

Type	ILD 1700-	2	10	20	40	50	100	200	250VT	500	750
Measuring range	mm	2	10	20	40	50	100	200	250	500	750
Start of measuring range	mm	24	30	40	175	45	70	70	70	200	200
Midrange (MMR)	mm	25	35	50	195	70	120	170	195	450	575
End of measuring range	mm	26	40	60	215	95	170	270	320	700	950
Linearity	FSO	±0.1 %	±0.08 %					±0.1 %	±0.25 %	±0.08 %	±0.1 %
Resolution <sup>1</sup>	μm	0.1	0.5	1.5	4	3	6	12	50	30	50
Measurement frequency programmable	2.5 kHz (1); 1.25 kHz (1/2); 625 Hz (1/4); 312.5 Hz (1/8)										
Light source (laser diode)	Wave length 670 nm, red, max. power 1 mW, laser class 2										
Permissible ambient light (at 2.5 kHz)	10.000 lx								15.000 lx	10.000 lx	
Spot diameter	SMR	80	110	320	230	570	740	1300	1500	1500	1500
	MMR	35	50	45	210	55	60	1300	1500	1500	1500
	EMR	80	110	320	230	570	700	1300	1500	1500	1500
Temperature stability	% FSO/°C	0.025	0.01					0.025	0.01		

Type	ILD 1700-	2	10	20	40	50	100	200	250VT	500	750
Operating temperature		0 ... +50 °C							0 ... +55 °C	0 ... +50 °C	
Storage temperature		-20 ... +70 °C									
Protection class		IP 65 (with plugged connection)									
Power supply $U_B$		24 V (11 ... 30 V) DC; max. 150 mA									
Measurement value output	selectable	4 -20 mA; 0 -10 V; RS422									
Voltage output		$R_i = 100 \text{ Ohm}$ , $I_{\max} = 5 \text{ mA}$ , short-circuit proof									
Load current output		$R_{\text{Load}} < (U_B - 6 \text{ V}) / 20 \text{ mA}$ , $R_{\text{Load}} 250 \text{ Ohm}$ for $U_B = 11 \text{ VDC}$									
Switching outputs	programmable	Error or/and limit values, short-circuit proof									
Switching inputs		Laser ON/OFF; Zero									
Synchronization	programmable	Simultaneous or alternating									
Sensor cable	Standard Extension	0.25 m (with cable jack) 3 / 10 m									
Electromagnetic compatibility (EMC)		EN 61326-1: 2006-10 DIN EN 55011: 2007-11 (Group 1, class B) EN 61 000-6-2: 2006-03									
Vibration (acc. to IEC 60068-2-6) <sup>2</sup>		2 g / 20 ... 500 Hz									
Shock (acc. to IEC 60068-2-29) <sup>2</sup>		15 g / 6 ms									
Weight (with 25 cm cable)		550 g		600 g		550 g			600 g		

The specified data apply to a white, diffuse reflecting surface (Reference: Ceramic).

SMR = Start of measurement range; MMR = Midrange; EMR = End of measuring range

FSO = Full Scale Output

1) At a measurement frequency of 2.5 kHz, without averaging

2) ILD1700-250VT: 20 g, vibration and shock resistant sensor model for use on vehicles

**optoNCDT1700 - for direct reflective surfaces**

Type	ILD 1700-	2DR	10DR	20DR
Measuring range	mm	2	10	20
Start of measuring range	mm	, see <a href="#">Fig. 16</a> , et seq.		
Midrange (MMR)	mm			
End of measuring range	mm			
Linearity, $\varphi/2$	FSO	$\pm 0.1 \%$	$\pm 0.1 \%$	$\pm 0.2 \%$
Linearity, $\varphi/2 \pm 0.3^\circ$	FSO	$\pm 0.2 \%$	$\pm 0.25 \%$	$\pm 2 \%^2$
Resolution <sup>1</sup>	$\mu\text{m}$	0.1	0.5	3
Tilt angle ( $\varphi/2$ )		$20^\circ$	$17.6^\circ$	$11.5^\circ$

Legend:  
mm (inches)

Not specified data correspond to those of the standard sensors.

MMR = Midrange

FSO = Full Scale Output

1) At a measurement frequency of 2.5 kHz, without averaging

2) Measuring range 18 (.71)

**optoNCDT 1700LL - for metallic shiny and rough surfaces**

Type	ILD 1700-	2LL	10LL	20LL	50LL
Measuring range	mm	2	10	20	50
Spot diameter	SMR	85 x 240 $\mu\text{m}$	120 x 405 $\mu\text{m}$	185 x 485 $\mu\text{m}$	350 x 320 $\mu\text{m}$
	MMR	24 x 280 $\mu\text{m}$	35 x 585 $\mu\text{m}$	55 x 700 $\mu\text{m}$	70 x 960 $\mu\text{m}$
	EMR	64 x 400 $\mu\text{m}$	125 x 835 $\mu\text{m}$	195 x 1200 $\mu\text{m}$	300 x 1940 $\mu\text{m}$

For measurements against high glossary surfaces (targets), resolution depends on the material.

Not specified data correspond to those of the standard sensors.

SMR = Start of measurement range; MMR = Midrange; EMR = End of measuring range

**optoNCDT 1710 - for long distance to the target**

Type		ILD 1710-50	ILD 1710-1000
Measuring range	mm	50	1000
Start of measuring range	mm	550	1000
Midrange (MMR)	mm	575	1500
End of measuring range	mm	600	2000
Linearity	mm	±0.05	±1
Resolution <sup>1</sup>	μm	5	100
Spot diameter	SMR	0.4 ... 0.5 mm	2.5...5 mm
	MMR	0.4 ... 0.5 mm	2.5...5 mm
	EMR	0.4 ... 0.5 mm	2.5...5 mm
Sensor cable		0.25 m integrated	
Weight		ca. 0.8 kg	
Protection class		IP 65	
Temperature stability	% FSO/ °C	0.01	
Operating temperature	°C	0 ... 50	

Not specified data correspond to those of the standard sensors.

SMR = Start of measurement range; MMR = Midrange; EMR = End of measuring range

FSO = Full Scale Output

1) At a measurement frequency of 2.5 kHz, without averaging

**optoNCDT 17x0BL**

Type	ILD	1700-20BL	1700-200BL	1700-500BL	1700-750BL	1710-50BL	1710-1000BL
Measuring range	mm	20	200	500	750	50	1000
Start of measuring range	mm	40	100	200	200	550	1000
Midrange	mm	50	200	450	575	575	1500
End of measuring range	mm	60	300	700	950	600	2000
Linearity	FSO	≤ ±0.08 %	≤ ±0.1 %	≤ ±0.08 %	≤ ±0.1 %		
Resolution <sup>1</sup>	μm	1,5	12	30	50	5	100
Measurement frequency	2.5 kHz; 1.25 kHz; 625 Hz; 312.5 Hz (adjustable)						
Light source	Semiconductor laser < 1 mW, 405 nm (blue purple)						
Laser protection class	Class 2 acc. to DIN EN 60825-1: 2008-05						
Light spot diameter (μm)	SMR, μm	320	1300	1500	1500	400 x 500	2.5 ... 5 mm
	MMR, μm	45	1300	1500	1500	400 x 500	2.5 ... 5 mm
	EMR, μm	320	1300	1500	1500	400 x 500	2.5 ... 5 mm
Weight (with 25 cm cable)	appr. 550 g		appr. 550 g	appr. 600 g	appr. 600 g	appr. 800 g	appr. 800 g

The specified data apply to a white, diffuse reflecting surface (Reference: Ceramic).

SMR = Start of measurement range; MMR = Midrange; EMR = End of measuring range

FSO = Full Scale Output

1) At a measurement frequency of 2.5 kHz, without averaging

### 3.5 Control and Indicator Elements

**i** **IMPORTANT!**  
 Keys can be locked via the serial interface, see Chap. 8.5.16.  
 For the meanings of the LEDs in setup mode, see Chap. 6.3.



Fig. 5 Keys and LED's on the sensor

(1) **select/zero** key Measurement mode:  
 Sets analog output to „Master“ or „Mid-point“, see Chap. 6.7, see Chap. 6.8.  
 Setup mode: For changing the sensor parameters, see Chap. 6.5.

(2) **function/enter** key  
 For switching between measurement mode and setup mode.

(3) LEDs, see Fig. 6.

**i** **IMPORTANT!**  
 If the function/enter key is pressed more than 5 sec, all parameters are overwritten by the factory settings.

LED		Color	Meaning
output	o		<b>Current (4 ... 20 mA)</b>
		red green	Voltage (0 ... 10 V) Serial (RS422)
speed	o		<b>Measurement frequency</b> <b>1 = 2.5 kHz</b>
		red green yel- low	1/2 = 1.25 kHz 1/4 = 625 Hz 1/8 = 312.5 Hz
	o		<b>Average: 1 (Median: 3)</b>
avg		red green yel- low	4 (5) 32 (7) 128 (9)
	o		<b>Average: 1 (Median: 3)</b>
zero		red flashing	Mid-point set / mastered Slave not synchronized
state	o		Laser off
		red green yel- low	Error O.K. MMR (midrange)

Fig. 6 Meanings of the LEDs in measurement mode

Note: In measurement mode (factory setting) only the LED „state“ lights up, subject to the current position of the object to be measured.

## 4. Delivery

### 4.1 Scope of Delivery

1 Sensor optoNCDT1700 with 0.25 m connecting cable and cable jack

2 Laser warning labels in accordance with IEC standards

1 Instruction manual

1 CD with driver and demo program

For ILD1700-xxDR: 1 fit-up aid (convenient to measuring range)

#### **Optional accessory, packed separately:**

1 PC1700 sensor cable, 3 m or 10 m in length, with cable plug and open cable ends (subject to order).

Check for completeness and shipping damage immediately after unpacking. In case of damage or missing parts, please contact the manufacturer or supplier.

### 4.2 Storage

Storage temperature: -20 up to +70 °C (-4 to +158 °F)

Humidity : 5 - 95 % (no condensation)

## 5. Installation

The sensor is an optical sensor for measurements with micrometer accuracy. Make sure it is handled carefully when installing and operating.

### 5.1 Sensor Mounting Diffuse Reflection

The sensor is mounted by means of 3 screws type M4. The bearing surfaces surrounding the fastening holes (through-holes) are slightly raised.


The laser beam must be directed perpendicularly onto the surface of the target. In case of misalignment it is possible that the measurement results will not always be accurate.

To align the sensor, please comply with the „Instructions for Operation“, see Chap. 9.3 especially.

If the sensors are to be used in soiled environments or in higher ambient temperatures than normal, MICRO-EPSILON recommends the use of protective housings, see Chap. 9.4.




**IMPORTANT!**  
Handle optical sensors with care.



*Fig. 7 Dimensional drawing  
optoNCDT 1700-2/10/20/50/100/200/250VT  
1700-2LL/10LL/20LL/50LL  
dimensions in mm (inches), not to scale*

MR	SMR	$\alpha$	$\epsilon$	A	B
2	24	35.0 °	44.8 °	25.8	16.8
10	30	34.3 °	35.6 °	28.7	20.5
20	40	28.8 °	26.7 °	30.1	22.0
50	45	26.5 °	18.3 °	31.5	22.5
100	70	19.0 °	10.9 °	32.6	24.1
200	70	19.0 °	7.0 °	33.1	24.1
250VT	70	19.0 °	6.0 °	33.5	24.1



*Fig. 8 Free space for optics*

SMR = Start of measuring range  
MR = Measuring range




Fig. 9 Dimensional drawing  
optoNCDT 1700-20/200BL  
dimensions in mm, not to scale

MR	SMR	$\alpha$	$\varepsilon$	A	B
20	40	28.8 °	26.7 °	30.1	22.0
200	100	13.5 °	6.3 °	33,1	24.1






Fig. 10 Free space for optics  
optoNCDT 1700-20/200BL  
dimensions in mm, not to scale

SMR = Start of measuring range  
MR = Measuring range



*Fig. 11 Dimensional drawing  
optoNCDT 1700-40/500/750  
optoNCDT 1700-500/750BL  
dimensions in mm, not to scale*



MR	SMR	$\alpha$	$\epsilon$
40	175	22.1 °	21.8 °
500	200	19.3 °	7.0 °
750	200	19.3 °	5.0 °

*Fig. 12 Free space for optics, ranges 1700-40/500/750 mm, ranges 1700-500/750BL mm, dimensions in mm (inches), not to scale*





Fig. 13 Dimensional drawing  
 optoNCDT ILD 1710-50/1000  
 optoNCDT ILD 1710-50/1000BL  
 dimensions in mm, not to scale



*Fig. 14 Free space for optics  
 optoNCDT ILD 1710-50/1000,  
 optoNCDT ILD 1710-50/1000BL,  
 dimensions in mm, not to scale*

MR	SMR	$\alpha$	$\epsilon$
50	550	13.35 °	15.15 °
1000	1000	7.45 °	4.65 °

## 5.2 Sensor Mounting Direct Reflection

The sensor is mounted by means of 3 screws type M4. The bearing surfaces surrounding the fastening holes (through-holes) are slightly raised.

Mount the sensor, that the reflected laser light hits the receiver element, see Fig. 16, see Fig. 17, see Fig. 18.

Use a fit-up aid to mount the sensor, see Fig. 15.




Fig. 15 Accessory to mount the sensor




Fig. 16 Dimensional drawings optoNCDT1700-2DR (not to scale)

**i** IMPORTANT!  
Handle optical sensors with care!

Legend:  
mm (inches)

Legend:  
mm (inches)





Fig. 17 Dimensional drawings optoNCDT1700-10DR (not to scale)

MR = Measuring range




Legend:  
mm (inches)

MR = Measuring range


Fig. 18 Dimensional Drawings range optoNCDT1700-20DR (not to scale)

### Mounting steps


- Switch on the operating voltage
- Watch the “State“ LED on the top side of the sensor, see Fig. 20.
- Position a shining or mirroring measuring object.



- Move the fit-up aid between sensor and measuring object.
- The “State“ LED illuminates yellow, see Fig. 20.
- Mount the sensor by means of 3 screws type M4.



- Remove the fit-up aid between sensor and measuring object.



### 5.3 Connector and Sensor Cable

Never bend the sensor cable by more than the bending radius of 60 mm.

The sensor comes with a permanently mounted connection cable of 0.25 m in length. Depending on where it is installed, a 3 m or 10 m sensor cable has to be attached to the connection cable.

MICRO-EPSILON recommends the use of the PC1700 standard sensor cable with a chain-type cable capability.

The connector and the cable component are marked with red markings which have to be aligned opposite each other before connection. In addition, they come with guidance grooves to prevent them from being wrongly connected. To release the plug-in connection, hold the plug-in connector on the grooved grips (outer sleeves) and pull apart in a straight line. Pulling on the cable and the lock nut will only lock the plug-in connector (ODU MINI-SNAP FP - lock) and will not release the connection. It is important, therefore, that the cable is never subjected to excessive pull force. If a cable of over 5 m in length is used and it hangs vertically without being secured, make sure that some form of strain-relief is provided close to the connector. Never twist the connectors in opposite directions to one another when connected.

Connect the cable shield to the potential equalization (PE, protective earth conductor) on the evaluator (control cabinet, PC housing) and avoid ground loops.

Never lay signal leads next to or together with power cables or pulse-loaded cables (e.g. for drive units and solenoid valves) in a bundle or in cable ducts. Always use separate ducts.

Recommended strand cross-section for self-made connection cables:  $\geq 0.14 \text{ mm}^2$  (AWG 25)

**i** Disconnect or connect the D-sub connection between RS422 and USB converter when the sensor is disconnected from power supply only.

### 5.4 Switching Inputs Laser On/Off, Setting Masters and the Mid-point

The switching inputs for Laser On/Off and Setting Masters / Mid-point are similarly wired.

**➡** Please connect Pin 9 and Pin 6 in order to activate the laser.

If the connection is released, the laser is deactivated.




Fig. 19 Switching examples for Laser Off, Mastering, Set Mid-point

## 6. Operation

### 6.1 Getting Ready for Operation

Install and assemble the optoNCDT1700 in accordance with the instructions set out, see Chap. 5. and connect with the indicator or monitoring unit and the power supply, having full regard to the connection instructions set out, see Chap. 6.3.

 **IMPORTANT!**

The laser diode in the sensor will only be activated if the input „Laser on/off“ is connected to GND.

The laser diode in the sensor can only be activated if the input „Laser on/off“ (Pin 9 or the red-blue wire in the sensor cable) is connected to GND.

Once the operating voltage has been switched on the sensor runs through an initialization sequence. This is indicated by the momentary activation of all the LEDs and the two switch outputs. If initialization has been finished, the sensor transmits the info string once in ASCII format via the serial interface independent of the selected interface. The initialization including the info string transmission takes up to 10 seconds. Within this period, the sensor neither executes nor replies commands.

To be able to produce reproducible measurements the sensor typically requires a start-up time of 20 minutes. Once this has elapsed the sensor will be in measurement mode and, in accordance with the factory settings, see Chap. 15.4, only the “state“ LED will be illuminated.

If the “state“ LED is not on, this means that

- either there is no operating voltage or
- the laser has been switched off.

#### **Operating Voltage**

- Nominal value: 24 VDC (11 ... 30 V, max. 150 mA).
- Use the power supply unit for measurement instruments only, and not for drive units or similar sources of pulse interference at the same time.

 Switch on the power supply unit, if wiring is done.

## 6.2 Membrane Keys




Fig. 20 Top view of the optoNCDT1700

The two membrane keys `function/enter` and `select/zero` have dual assignments, depending on the operating status.

### Measurement mode (normal operation):

- `zero` key:
  - Sets the analog output to the value for the mid-point of the measurement range, i.e. 5 VDC or 12 mA.
  - Pressing the `zero` key again resets the function, see Chap. 6.7, see Chap. 6.8.
- `function` key:
  - Switches the sensor to setup mode, see Chap. 6.5.

Pressing and holding the `function/enter` key for longer than 5 seconds overwrites all the parameter values with the factory settings (default values, see Chap. 15.4).

### Setup mode („function“ key actuated):

- `function` key:
  - For running through the levels and parameters.
- `select` key
  - To open the selection list and
  - select the value of the parameter in sequence.
- `enter` key:
  - For saving the selected parameter value and
  - Returning to measurement mode.

If approximately 15 seconds have elapsed since the last press of the `function` key or 30 seconds since the last press of the `select` key, the sensor returns to measurement mode without changing the parameters.

### **i** IMPORTANT!

In setup mode the sensor continues to send measurement values to the output.

The LEDs on the sensor, see Fig. 20, have different indicator functions depending on whether the sensor is in measurement mode or setup mode.

### 6.3 LED-Functions

LED	Status	Measurement mode	Setup mode
state	illuminated	Object is in the measurement range or error	...
	off		Sensor off or laser off
	flashes slowly	...	Selected parameter value matches the saved value
	flashes quickly	...	Selected parameter value does not match the saved value
output speed avg	illuminated or flashing	Indication of the parameter value from level 1	Selected parameter value
	flashing red		Status „off“
zero	illuminated		Sensor „master“ or „set to mid-point“
	off		Normal operation
	flashing		Sensor as slave without synchronous signal

### 6.4 Inputs and Outputs

Signal	Pin	Explanation	Configuration
Analog output	13	Current 4 ... 20 mA	$R_{Limit} < (U_B - 6 V) / 20 \text{ mA}$ ; $R_{Limit \text{ max.}} = 250 \text{ Ohm}$ with $U_B = 11 V$
		Voltage 0 ... 10 VDC	$R_i = 100 \text{ Ohm}$ , $I_{max} = 5 \text{ mA}$ , short-circuit protection from 7 mA, <sup>2</sup>
Laser on/off	9	Switching input	Laser operates if pin 9 is connected with GND
Zero	10	Switching input, Chap. 6.7	Connect 0.5 ... 3 s with GND: SET, connect 3 ... 6s with GND: RESET
Switching output 1	8	Error or limit output 1	Open-Collector (NPN), $I_{max} = 100 \text{ mA}$ , $U_{max} = 30 \text{ VDC}$ , Interrupt supply voltage to cancel the short-circuit protection
Switching output 2	7	Limit output 2	
Sync +/Sync	3/4	Synchronizaton <sup>1</sup>	Symmetrical synchron output (Master) or synchron input (Slave)
Tx +/Tx -	1/2	Serial output RS422	Terminate with 120 Ohm receive-site
Rx +/Rx -	12/11	Serial input RS422	Internally terminated with 120 Ohm

**i** **IMPORTANT!**

Disconnect or connect the D-sub connection between RS422 and USB converter when the sensor is disconnected from power supply only.

- 1) Input is used for triggering in trigger mode, see Chap. 6.14.
- 2) The use of a 10 nF capacitance at the entrance for interference suppression is recommended.

**i** **IMPORTANT!**

- Parameters for  
 - Output type  
 („Measurement value output“)  
 - Measurement frequency  
 - Average number  
 - Analog error


The system returns to measurement mode without saving the parameters:

- if 15 seconds elapse after the last press of the function/enter key.

- if 30 seconds elapse after the last press of the select/zero key.

## 6.5 Menue, Setting the Parameters

The sensor parameters can be set in setup mode using the function/enter and select/zero keys.




**i IMPORTANT!**

- Parameters for Synchronization
- Averaging type
- Operation mode
- Trigger mode
- Baud rate
- Data format

The system returns to measurement mode without saving the parameters:

- if 15 seconds elapse after the last press of the function/enter key
- if 30 seconds elapse after the last press of the select/zero key.



1) Depends on operation mode settings (synchronization or trigger).

## 6.6 Average Setting

The optoNCDT1700 is supplied ex factory with the default setting „moving averaging, number of averaging N = 1“ (no averaging activated).

Averaging methods:

- Moving average
- Recursive average
- Median

The purpose of averaging is to:

- Improve the resolution
- Eliminate signal spikes
- „Smooth out“ the signal.

Averaging has no effect on linearity.

### 6.6.1 Averaging Number N

In every measurement cycle (at a measurement frequency of 2.5 kHz every 0.4 ms) the internal average is calculated anew. The averaging number N indicates the number of consecutive measurement values to be averaged in the sensor.

**i** **IMPORTANT!**  
The preset average value and the number of averaging are saved after switching off.

Averaging type	Averaging number	LED „avg“
moving	1 (no averaging)	
recursive	1 (no averaging)	off
Median	3	
moving	4	
recursive	4	red
Median	5	
moving	32	
recursive	32	green
Median	7	
moving	128	
recursive	128	yellow
Median	9	

In setup mode the averaging number can be set to 4 different, predefined fixed values. Further details on these, see Chap. 6.5. The selected averaging number is also indicated in measurement mode by the “avg” LED, see Fig. 21.

Averaging does not affect the measurement frequency or data rates in digital measurement value output.

More averaging counts can also be used if programmed via the digital interface, see Chap. 8.5.4.

*Fig. 21 Specification of the averaging count*

The averaging is recommended for static measurements or slowly changing measuring values.

### 6.6.2 Moving Average (Default Setting)

The selected number N of successive measurement values (window width) is used to generate the arithmetic average value  $M_{gl}$  on the basis of the following formula:

$$M_{gl} = \frac{\sum_{k=1}^N MV(k)}{N}$$

$MV$  = Measuring value  
 $N$  = Averaging number  
 $k$  = Running index  
 $M_{gl}$  = Averaging value respectively output value

#### Mode:

Each new measurement value is added and the first (oldest) measurement value from the averaging process (from the window) taken out again. This results in short transient recovery times for jumps in measurement values.

Example:  $N = 4$

$\dots 0, 1, \underline{2, 2, 1, 3}$ $\downarrow$ $\frac{2, 2, 1, 3}{4} = M_{gl}(n)$	$\dots 1, 2, \underline{2, 1, 3, 4}$ $\downarrow$ $\frac{2, 1, 3, 4}{4} = M_{gl}(n+1)$	Measurement value    Output value
--------------------------------------------------------------------------------------------	----------------------------------------------------------------------------------------------	-----------------------------------------------

Standard values for N: The values  $N = 1, 4, 32, 128$  are permanently stored in the sensor. For other permissible values for N, see Chap. 8.5.4.

#### Characteristics:

The sliding average in the optoNCDT1700 can only be generated for up to a maximum of 128 values.

### 6.6.3 Recursive Average

Formula

$$M_{\text{rek}}(n) = \frac{MV_{(n)} + (N-1) \times M_{\text{rek}(n-1)}}{N}$$

MV = Measuring value  
 N = Averaging number  
 n = Measurement value index  
 M<sub>rek</sub> = Average value respectively output value

#### Mode:

Each new measurement value MV(n) is added, as a weighted value, to the sum of the previous measurement values M<sub>rek</sub>(n-1).

Standard values for N: The values N = 1, 4, 32, 128 are permanently stored in the sensor. For other permissible values for N, see Chap. 8.5.4 „Averaging“.

#### Characteristics:

The recursive average permits a high degree of smoothing of the measurement values. However, it requires extremely long transient recovery times for steps in measurement values. The recursive average shows low-pass behavior.

### 6.6.4 Median

The median is generated from a pre-selected number of measurement values. To do so, the incoming measurement values (3, 5, 7 or 9 measurement values) are resorted again after every measurement. The average value is then given as the median. In generating the median in the controller, 3, 5, 7 or 9 measurement values are taken into account, i.e. there is never a median of 1.

This permits individual interference pulses to be repressed, but the measurement value curve is not smoothed to any great extent.

Example: Average from five measurement values

... 0 1 2 4 5 1 3 → Sorted measurement values: 1 2 **3** 4 5      Median<sub>(n)</sub> = 3

... 1 2 4 5 1 3 5 → Sorted measurement values: 1 3 **4** 5 5      Median<sub>(n+1)</sub> = 4

**IMPORTANT!**

“Master” is only available in “Switch mode” and “Set mid-point” is only available in “Error mode”, see Chap. 6.5.

“Master” or “Set mid-point” requires that an object to be measured is within the measurement range.

„Master“ has an influence on the analog and digital output.

## 6.7 Setting Masters

“Mastering” enables the measurement values at the sensor output (analog/digital) to be compared with a known measurement object (master). This function is primarily used for comparison of mounting tolerances. The value which is given during measurement on the sensor output of the “mastering object” is the “master value”. This involves the parallel displacement of the sensor’s characteristic curve.

### Storing of the master value in the sensor:

This master value has to be inserted and stored in the sensor before mastering. Currently, there are two possibilities:

1. In the configuration program “ILD1700 Tool“, see Chap. 10..
2. Command „Set\_LIMITS“, see Chap. 8.5.7, (Set limit values) as digital value in the „master value“. A detailed description of the calculation, see Chap. 7.3.

Therefore the master value is available even after a restart of the sensor. Detailed information, see Chap. 8.5.20 “Enable / Lock the Flash for Setting Masters and the Mid-Point”. In the case that the sensor configuration is set to „permanent in flash“, the master value can permanently be solved in the sensor in the ILD1700 tool.

The displacement of the characteristic curve reduces the usable measurement range of the sensor the further the master value is away from the master position.

### Advice:

In the case of a new ILD1700 sensor 0.5 x measuring range is set as the master value. Resetting to factory settings also includes that the master value is set to 0.5 x measuring range.

The action „mastering“ can be activated in three different ways:

- Press the button `zero/select` on the sensor. Afterwards the red LED flashes “Zero”. The initial state is reached by a second press.
- External Low-Signal at the input “Zero”:  
Connect GND 0.5 ... 3 s: SET (mastering),  
Connect GND 3 ... 6 s: RESET (reset)
- At Firmware version 6.000 using the command “SETZero”, see Chap. 8.5.21.  
using parameters  $x = 1 \Leftrightarrow$  setting  $\Leftrightarrow$ ;  
using parameters  $x = 0 \Leftrightarrow$  reset

<b>Sequence</b>	<b>„Mastering“</b>
Operation mode	switch-mode
Setpoint value	Programmed master value
Step 1	Move object to be measured and sensor to desired position relative to one another.
Step 2	Press <b>Zero</b> key once or connect the “Zero” input to GND for 0.5 up to 3 s or command „SetZero“ <sup>1</sup> .
<b>Output signals after “Mastering”</b>	
Indicator	LED „zero“ lights up.
Analog value	$U_{out, M} = \frac{\text{Master value} \cdot 10 \text{ V}}{\text{Measurement range}}$ $I_{out, M} = \frac{\text{Master value} \cdot 20 \text{ mA}}{\text{Measurement range}}$
Digital value	$D_A = \text{Master value}$

Fig. 23 Sequence for mastering

**Example:**

Measurement range 50 mm, voltage output 0 ... 10 V

Master value 17 mm, related to the centre of the measurement range (MR) = 5 V,

Analog value during mastering: 3.4 V

After the mastering, the sensor gives new measurement values, related to the master value. The non-mastered condition applies by means of a reset.

1) Possible at Firmware version 6.0




Fig. 22 Characteristic for mastering

## 6.8 Setting Mid-Point

The function „Setting mid-point“ displaces the analog measurement value to the value for the mid-point of the measurement range, so +5 V respectively 12 mA.

The action „set mid point“ can be activated in three different ways:

- Press the button *Zero/Select* on the sensor. Afterwards the red LED flashes “Zero”. The initial state is reached by a second press.
- External Low-Signal at the input “Zero”.  
Connect GND 0.5 ... 3 s: SET (mid-point)  
Connect GND 3 ... 6 s: RESET (reset)  
At firmware version 6.000 using the command “SETZero”, see Chap. 8.5.21  
using parameters  $x = 1 \Leftrightarrow$  setting  $\Leftrightarrow$  ;  
using parameters  $x = 0 \Leftrightarrow$  reset

### IMPORTANT!

“Master“ is only available in “Switch mode“ and “Set mid-point“ is only available in “Error mode“, see Chap. 6.5.

“Master“ or “Set mid-point“ requires that an object to be measured is within the measurement range.

“Set Midpoint“ has an influence on the analog and digital<sup>1</sup> output.

Sequence	„Set mid-point“
Operation mode	error-mode
Setpoint value	Centre of the analog area
Step 1	Move object to be measured and sensor to desired position relative to one another.
Step 2	Press <i>Zero</i> key once or connect the “Zero” input to GND for 0.5 up to 3 s or command “SetZero” <sup>1</sup> .
<b>Output signals after “Set mid-point”</b>	
Indicator	„Zero“ LED lights up.
Analog values	$U_A = 5 \text{ V}$ or $I_A = 12 \text{ mA}$
Digital value	$D_A = 8184$

Fig. 24 Sequence for setting the mid-point

1) Possible at Firmware version 6.0

**Example:**

Measurement range 50 mm, voltage output 0 ... 10 V  
 Mid-point is set at the position  $x_m = 10$  mm  
 Set mid-point results in an output signal of 5 V.

**Remaining measurement range respectively output range:**

$x_{max} = 35$  mm

$Out_{min} = 3$  V respectively 8.8 mA

After setting mid-point the sensor gives new measurement values, related to the mid-point.

The condition before setting mid-point can be achieved by a reset.

Set mid-point (only error mode): no limit control

The displacement of the characteristic curve reduces the usable measurement range of the sensor.




Fig. 25 Characteristic for setting the mid-point

**i** **IMPORTANT!**

Synchronized sensors must always be set to the same measurement frequency.

Please, see Chap. 15.1.

**Recommendations:**

- Use a high measurement frequency for light colored and matt objects to be measured.
- Use a low measurement frequency for dark or shiny objects to be measured (e.g. surfaces covered in black lacquer), for better measurement results.

### 6.9 Frequency and Output Rate

The measurement frequency defines the number of measurements performed by the sensor per second. The measurement frequency may be 2.5 kHz, 1.25 kHz, 625 Hz or 312.5 Hz. Details of how to change the measurement frequency, see Chap. 6.5.

The output rate gives the actual number of measurement values at the sensor output per second. The maximum output rate can never exceed the measurement frequency.

Output	Maximum output rate
Current	Measurement frequency
Voltage	Measurement frequency
RS422	Output rate Measurement frequency; Dependent on the transmission rate (baud rate) and data format (ASCII-Code).

The sensor continues to measure internally but holds back the output until the last measurement value has been issued in full. The next measurement value is the last valid value, with other values between being lost.

*Fig. 26 Output rates for the output types*

Calculation of the output rate using the RS422 serial interface:

$$\text{Output rate} = \text{Measuring frequency } n$$

$$n = \text{int} (b * 11 * \text{MR} / \text{BR}) + 1$$

The values are summarized, see Chap. 15.1.

Abbreviations used:

n = Partial factor

int = Integral part of ( )

b = Byte/measurement value

(binary format b=2, ASCII b=6)

MR = Measurement frequency [Hz]

BR = Baud rate [Baud]

Example:

Measurement frequency = 1250 Hz, ASCII-Format (b=6), Baud rate = 19200 Baud

-->  $n = \text{int} (4.3) + 1 = 5$

-->  $\text{Output rate} = 1.25 \text{ kHz} / 5 = 250 \text{ Hz}$ .

## 6.10 Operation Mode

### 6.10.1 Error Mode (Error Control)

In error mode, the switching output 1 is used as an error output. The switching output 2 remains inactive. The error mode can be programmed using both the keypad and the programming interface.

The error output is activated (conducting to GND) when:

- the object to be measured is outside the measurement range, see Fig. 27,
- there is no object to be measured present, or
- if the object to be measured is unsuitable (too dark, polished metal, insufficiently reflective).

Transparent objects can be penetrated by the light of the laser and the laser spot unacceptably enlarged, resulting in unreliable measurements. This will also trigger the error output.

### 6.10.2 Switch Mode

(Limit Control)

In switch mode, both switching outputs are used as limit switches, see Fig. 28.

The individual limits can be programmed using the digital programming interface, see Chap. 8.5.7, see Chap. 8.5.8.

8.5.7, see Chap. 8.5.8.




Fig. 27 Signal sequence for the switching outputs in the operation mode „Sync error“ and „Trigger error“

Error mode: Setting mid-point only, no limit control

Switch mode: Mastering only, limit control

**i** **IMPORTANT!**  
The limit control is based on the average.

The following four values are used:

- Upper limit (UL),
- Lower limit (LL),
- Upper hysteresis value (UH),
- Lower hysteresis value (LH).

If the upper limit is exceeded the assigned switching output 1 will be activated (conducting), and deactivated again with the follow-on shortfall on the upper hysteresis value. The same applies in principle to a shortfall on the lower limit and switching output 2, see Fig. 28.

**Standard setting**

Upper limit (UL):  
101 % FSO / Digital value: 16365

Upper hysteresis value (UH):  
100 % FSO / Digital value: 16207

Lower hysteresis value (LH):  
0 % FSO / Digital value: 161

Lower limit (LL):  
-1 % FSO / Digital value: 0

In switch mode, both switching outputs are activated when:

- the object to be measured is outside the measurement range, see Fig. 28,
- there is no object to be measured present, or
- if the object to be measured is unsuitable (too dark, polished metal, insufficiently reflective).





Fig. 28 Signal sequence for the switching outputs in operation mode „Sync switch“ and „Trigger switch“

### 6.10.3 Output Circuit for the Switching Outputs

**! WARNING!**  
 Never connect the relay without a protective diode! Risk of damage to the switch output.



In the active state the transistor T is conductive. The switch outputs are short-circuit-proof.

To reset the short-circuit protection:

- Clear the external short circuit
- Switch off the sensor and switch on again, or
- Send the software command “Reset” to the sensor.

The two limit outputs (Pin 7 and 8) may also be actuated in parallel as window comparator (OK/Not OK separation).

*Fig. 29 Switching output: Examples of external protective circuit with pull-up resistor or relay with protective diode*

### 6.11 Synchronization of Sensors

If two sensors are used on a single object to be measured, they can be synchronized with each other. The optoNCDT1700 distinguishes between two types of synchronization, see [Fig. 30](#).

**i IMPORTANT!**  
 Synchronization requires that the master and slave sensors have the same measurement frequency.

Type		Used for
Simultaneous synchronization	Both sensors measure in the same cycle.	Measurement of differences (thickness, difference in height) on opaque objects. Here, Sensor 1 must be programmed as the “Master” and Sensor 2 as the “Slave”.
Alternating synchronization	Both sensors measure alternately	Thickness measurements on translucent objects or measurements of difference on closely spaced measurement points. The alternating synchronization requires that the lasers are switched on and off alternately so that the two sensors do not interfere with each other optically.

*Fig. 30 Characteristics of and uses for the different types of synchronization*

For alternating synchronization the master sensor has to be run in „Master alternating“ mode, see [Chap. 6.5](#).

**i** **IMPORTANT!**


The slave sensor should be operated unsynchronized as far as possible!

**!** **WARNING!**

The synchronous terminals must never be connected to the operating voltage and/or GND, even momentarily. Risk of permanent damage from overloading!

- 1) Connect the ground connectors (GND, pin 6, black) of the sensors if the sensors are not operated on the same power supply.

Although this does not change the measurement frequency, the output rate is reduced by half in this mode. An unsynchronized slave switches the laser off, sends an accordant error signal.



Conductors twisted together in the cable must be used for synchronization. Terminals with the same polarity (Sync+ and Sync-) should be connected.

The optoNCDT1700 contains a terminating resistor, see Fig. 31, between pin 3 and 4 for line matching.

*Fig. 31 Synchronization of two optoNCDT1700*

**Synchronization with external signal**

If a sensor is synchronized with an external signal the levels of the signal must comply with the LVDS specifications (Low Voltage Differential Signals). Further information, see Chap. 6.14.3. The synchronization frequency is to maintain with a tolerance of  $\pm 1\%$  of the measurement frequency.

Triggering is done with an accordant hardware only. Use the optional available triggerBOX1700 from MICRO-EPSILON.

**6.12 Exposure Time**

At a maximum measurement frequency of 2.5 kHz the CCD element is exposed 2500 times per second. This gives a predefined maximum exposure time (laser exposure time) of 0.4 ms at this measurement frequency. The lower the measurement frequency, the longer the maximum exposure time.

The real-time control of the sensor reduces the exposure time in dependency on the amount of light hitting the CCD element and therefore compensates for reflection changes at the same time, e.g. caused by imprints on the surface of the object being measured.

### 6.13 Timing, Measurement Value Flux

The controller operates internally with real time cycles in a pipeline mode:

1. Exposure: Charging the image detector in the receiver (measurement).
2. Reading: Reading out of the imaging device and converting into digital data.
3. Computation: Measurement computation.
4. Controlling

The output through the analog and digital interface starts with the beginning of every new cycle. The analog value and digital switch outputs are updated immediately and the digital output starts with the start bit.

Each cycle takes  $400\ \mu\text{s}$  at a measuring rate of  $2.5\ \text{kHz}$  (speed=1). The measured value N is available after each cycle with a constant lag of four cycles in respect to the real time event. The delay between the input reaction and the signal output is therefore 1.2 up to 1.6 ms. The processing of the cycles occurs sequentially in time and parallel in space, see [Fig. 32](#), pipelining). This guarantees a true constant real time data stream.

Cycle	1.	2.	3.	4.	5.
Time	$400\ \mu\text{s}$	$800\ \mu\text{s}$	$1200\ \mu\text{s}$	$1600\ \mu\text{s}$	$2000\ \mu\text{s}$
1. Layer	Exposure N (Output N-4)	Reading N	Computation N	Controlling N	Exposure N+4 (Output N)
2. Layer	Controlling N-3	Exposure N+1 (Output N-3)	Reading N+1	Computation N+1	Controlling N+1
3. Layer	Computation N-2	Controlling N-2	Exposure N+2 (Output N-2)	Reading N+2	Computation N+2
4. Layer	Reading N-1	Computation N-1	Controlling N-1	Exposure N+3 (Output N-1)	Reading N+3

*Fig. 32 Sensor timing*




Fig. 33 Measurement value flux ILD 1700

### **i** IMPORTANT!

Triggering is done with an accordant hardware only. Use the optional available triggerBOX1700 from MICRO-EPSILON.

### **i** IMPORTANT!

The limit control is activated only in the operation mode „Trigger switch mode“.

## 6.14 Triggering

### 6.14.1 Basics

The optoNCDT1700 measurement output is controllable through an external signal (electrical signal or command). Thereby the analog or digital output is affected only. Triggering does not influence the measuring frequency respectively the timing, see Chap. 6.13, so that between the trigger event (level change) and the output reaction always lie 4 cycles.

The synchronization inputs are used for external triggering. So the sensors can alternatively be synchronized or triggered. The change between **synchronization** (default setting) and **triggering** is done with the keys, see Chap. 6.5, „Operation mode“ or the SET\_ERROROUTPUT command, see Chap. 8.5.9.

### 6.14.2 Trigger Modes

The measurement output in trigger mode can be controlled with the **edge** as well as the **level** of the trigger signal. Implemented trigger conditions:

- Rising edge,
- Falling edge,
- High level or
- Low level.

Set the trigger conditions (edge or level) with the keys, see Chap. 6.5, „Synchronization“ or the SET\_TRIGGERMODE command, see Chap. 8.5.13.

#### Edge triggering

The analog output is updated after a trigger edge. If the digital output is selected only a single digital value, see Fig. 34, is transmitted through the RS422 interface. Between the analog output is temporarily stopped (‘‘Sample and hold‘‘, see Fig. 35.




Fig. 34 Rising trigger edge (above) and digital output signal (below)

### Level Triggering

So long measurements are transmitted as the trigger condition is fulfilled.

The GET\_MEASVALUE command, see Chap. 8.5.19, supplies the specified amount of digital measurements which must be defined in the related parameter. Digital measurements are output in binary, see Chap. 8.2.1 or ASCII format, see Chap. 8.2.2, in trigger mode.

#### 6.14.3 Trigger Signal Levels

The inputs (Trig+, Trig-, see Fig. 40) are used for external triggering. The necessary signal levels comply to the LVDS (Low Voltage Differential Signals) specification. Thus only LVDS driver circuits with 3.3 V operation voltage are used for triggering.

The difference between both input signals Trig+ (pin 3) and Trig- (pin 4) must be according to amount greater than 100 mV. Each individual signal may lie in the range between 0 V and +2.9 V related to GND. The sensor detects a high level, see Fig. 37, if the voltage on Trig+ is greater than on Trig-. The optoNCDT1700 contains a terminating resistor, see Fig. 38, between pin 3 and 4 for line matching.

#### 6.14.4 Trigger Pulse

The trigger pulse duration  $t_d$  must be one cycle time ( $= 1 /$  measuring frequency) at least. Shorter measuring frequencies need a longer trigger pulse duration (e.g. from  $t_d = 400 \mu\text{s}$  with speed = 1 up to  $t_d = 3.2 \text{ ms}$  with speed = 1/8).

- $t_d$  Pulse duration
- $t_n$  Non-pulse period
- $t_i$  Pulse interval
- $U_i$  Input signal level




Fig. 35 High trigger level (above) and analog output signal (below)



Fig. 36 Low trigger level (above) and digital output signal (below)




Fig. 37 Timing trigger signal

**i** **IMPORTANT!**

Exceeding the maximum trigger frequency leads in measuring inaccuracy shown by the flashing zero LED and the set error output (if operation mode trigger/error is selected).

**i** **IMPORTANT!**

Triggering is done with an accordant hardware only. Use the optional available triggerBOX1700 from MICRO-EPSILON.

**i** **IMPORTANT!**

Connect the trigger source ground with the sensor ground (GND, pin 6) before sending trigger signals.

**Edge triggering**

The pulse interval  $t_i$  between two trigger pulses must be at minimum four cycles. Then the triggered measurement is issued before a new trigger edge arrives. This results in a maximum trigger frequency of 625 Hz for a measuring frequency of 2.5 kHz.

**Level triggering**

If the trigger level has changed, all measurements must be issued before a new trigger lever can be identified. The sensor requires a non-pulse period  $t_n$  of 4 cycles. The minimum pulse interval amounts therefore 5 cycles ( $t_i = t_d + t_n$ ), see Fig. 39. This results in a maximum trigger frequency of 500 Hz for a measuring frequency of 2.5 kHz.

Trigger mode	Edge triggering	Level triggering
Pulse duration $t_d$	1 Cycle = 400 $\mu$ s	1 Cycle = 400 $\mu$ s
Non-pulse period $t_n$	3 Cycles = 1.2 ms	4 Cycles = 1.6 ms
Pulse interval $t_i$	4 Cycles = 1.6 ms	5 Cycles = 2.0 ms
Trigger frequency $f_T$	$f_T = f_M / 4 = 625$ Hz	$f_T = f_M / 5 = 500$ Hz

Fig. 39 Minimum pulse values and maximum trigger frequency for speed = 1

**6.14.5 Pin Assignment for External Trigger Signal**

Pin	Input	Characteristics	Color sensor cable PC1700-x
3	Trigger +	Differential input	blue
4	Trigger -		pink
6	GND	System ground	black





Fig. 38 Trigger wiring

$f_M$  = Measurement frequency



View on solder-pin side male cable connector, insulator

Fig. 40 Pin assignment for external trigger signal

A 10 nF ceramic capacitor between analog output and AGND of subsequent devices reduces highfrequency interferences.

## 7. Measurement Value Output

The optoNCDT1700 can issue the measurement values either via the analog output or the RS422 serial interface. The two different types of output cannot be used concurrently. The analog output can be programmed for use as a current output or a voltage output.

### 7.1 Voltage Output

Range for measurement voltages -0.1 V ... +10.1 V

Output amplification  $\Delta U_{OUT}$  10.0 V = 100 % Measuring range

Error value: 10.2 V ( $\pm 10$  mV)

Calculation of a measurement value x in mm from analog voltage:

$$x \text{ [mm]} = U_{OUT} * \frac{MR \text{ [mm]}}{10.0 \text{ [V]}}$$

Reference value: SMR

$$x \text{ [mm]} = U_{OUT} * \frac{MR \text{ [mm]}}{10.0 \text{ [V]}} - MR/2$$

Reference value: MMR

Example: Measuring range = 10 mm,  $U_{OUT} = 4.6$  V; Result:  $x = 4.6$  mm respectively  $x = -0.4$  mm

SMR = Start of measuring range

MMR = Midrange

EMR = End of measuring range

MR = Measuring range




Fig. 41 Voltage output signal

## 7.2 Current Output

Max. range	4 mA ... 20 mA
Output amplification $\Delta I_{OUT}$	16 mA = 100 % Measuring range
Error value:	3 mA ( $\pm 3 \mu A$ )

Calculation of measurement value x in mm from analog current

Reference value SMR:

$$x \text{ [mm]} = (I_{OUT} - 4 \text{ mA}) * \frac{MR \text{ [mm]}}{16 \text{ [mA]}}$$

Reference value MMR:

$$x \text{ [mm]} = (I_{OUT} - 4 \text{ mA}) * \frac{MR \text{ [mm]}}{16 \text{ [mA]}} - MR/2$$

Example: Measuring range = 10 mm,  $I_{OUT} = 12 \text{ mA}$ ; Result: x = 5 mm respectively x = 0 mm

## 7.3 Digital Value Output

The digital measurement values are issued as unsigned digital values (raw values).

Digital value	Used for
0 ... 16367	Value range
0 ... 160	SMR back-up (1 %)
161 ... 16207	Measurement range

Digital value	Used for
16208 ... 16367	EMR back-up (1 %)
16370 ... 16383	Error codes

Calculation of a measurement value in mm from digital output

Reference value SMR:

$$x \text{ [mm]} = (\text{digital}_{OUT} * \frac{1.02}{16368} - 0.01) * MR \text{ [mm]}$$

Reference value MMR:

$$x \text{ [mm]} = (\text{digital}_{OUT} * \frac{1.02}{16368} - 0.51) * MR \text{ [mm]}$$

Example: MR = 10 mm, Reference value = SMR

Digital value	Conversion	Measurement value
8184	$(8184 * 6.23167e-5 - 0.01) * 10 \text{ mm}$	= 5 mm (=MMR)
10261	$(10261 * 6.23167e-5 - 0.01) * 10 \text{ mm}$	= 6.294 mm
161	$(161 * 6.23167e-5 - 0.01) * 10 \text{ mm}$	= 0 mm (=SMR)

Note: A digital value can be calculated from a measurement value (millimeter) as follows:

$$\text{digital}_{\text{OUT}} = \left[ \frac{x \text{ [mm]}}{\text{MR [mm]}} + 0.01 \right] * \frac{16368}{1.02}$$

This formula can be used, for example, in the programming of switching thresholds, see Chap. 8.5.7.

### 7.4 Digital Error Modes

Digital error codes are issued in the same way as measurement values.

Value range for error codes:  
16370 ... 16383 (digital OUT)

- F1 bad object
- F2 out of range -
- F3 out of range +
- F4 poor target
- F5 Laser off
- 16370 No object detected
- 16372 Too close to sensor
- 16374 Too far from sensor
- 16376 Object cannot be evaluated
- 16378 external laser off
- 16380 Sensor in trigger mode
- Trigger pulses come to fast.

## 8. Serial Interface RS422




Fig. 42 System structure to operate the interface card IF2008

	Pin	Signal	Signal	Pin		
Sensor 1 14-pol. ODU-con- nector	5	24 V	24 V supply <sup>1</sup>	10	IF2008, X1 and X2, 15-pol. Sub-D	
	12	Rx + (Input)	Sensor 1/3 TxD +	2		
	11	Rx - (Input)	Sensor 1/3 TxD -	1		
	1	Tx + (Output)	Sensor 1/3 RxD +	4		
	2	Tx - (Output)	Sensor 1/3 RxD -	3		
	3	Sync +	TRG +	6		
	4	Sync -	TRG -	7		
6	GND	GND	15			
When using 3 sensors apply the optional available Y-adapter cable IF2008-Y.						
Sensor 2 14-pol. ODU con- nector	5	24 V	24 V supply <sup>1</sup>	10		
	12	Rx +	Sensor 2/4 TxD +	12		
	11	Rx -	Sensor 2/4 TxD -	11		
	1	Tx +	Sensor 2/4 RxD +	14		
	2	Tx -	Sensor 2/4 RxD -	13		
	3	Sync +	TRG +	6		
	4	Sync -	TRG -	7		
6	GND	GND	15			

Required cables and program routines

- IF2008  
RS422 interface card, for 1 to 4 laser-optic sensors from the ILD1700 series and 2 encoders, including MEDAQLib programming interface.
- PC1700-x/IF2008  
Power supply and output cable, x = length with 3, 6 or 8 m.

Alternatively, data can be transferred with the demo software (ILD1700 Tool) and a RS422 converter to USB, see Chap. 10..

Fig. 43 Pin assignment for two PC1700-x/IF2008 and IF2008

1) Supply voltage for the connected sensors and encoders, output current 1.25 A max.

## 8.1 Interface Parameters

The optoNCDT1700 comes with a RS422 serial interface to enable the sensor to be operated from a standard computer and measurement values and error codes to be transferred.

Data format: 8 Data bits, no parity, one stop bit (8,N,1)

The factory-set baud rate is 115.2 kBaud but it can be programmed to a different value, see Chap. 6.5. The maximum measurement frequency is 2.5 kHz.

## 8.2 Data Format for Measurement Values and Error Codes

### 8.2.1 Binary Format

The data word is comprised of two consecutive bytes (H-byte/L-byte). One flag bit in each byte differentiates a high from a low byte.

Start	1	7 Bit MSB	Stop	Start	0	7 Bit LSB	Stop
-------	---	-----------	------	-------	---	-----------	------

Conversion of the binary data format:

For conversion purposes the high and low bytes must be identified on the basis of the first bit (flag bit), the flag bits deleted and the remaining 2 x 7 bits compiled into 14 bit data word.

Reception:

H-Byte	1	D13	D12	D11	D10	D9	D8	D7
L-Byte	0	D6	D5	D4	D3	D2	D1	D0

Result of conversion

0	0	D13	D12	D11	D10	D9	D8	D7	D6	D5	D4	D3	D2	D1	D0
---	---	-----	-----	-----	-----	----	----	----	----	----	----	----	----	----	----

Conversion must be done in the application program.

Example:

Digital value: 2099 (= 0x0833 = 0b0010000 0110011)                      14 Bit

Binary format

H-Byte: Transfer 0x90 (0b10010000)                      with flag bit                      8 Bit

-> converted 0x10 (0b0010000)                      without flag bit                      7 Bit

L-Byte: Transfer 0x33 (0b00110011)                      with flag bit                      8 Bit

-> converted 0x33 (0b110011)                      without flag bit                      7 Bit

Flag bits deleted and compiled: 0x833

### 8.2.2 ASCII Format

Output of 5 characters (digits) in ASCII code for the digital value + 1 tag „CR“ (= 0x0D), i.e. a total of 6 characters. Digital values with just 3 or 4 digits are preceded by blank characters.

Example: Digital value 2099

Transfer: “ \_2099“ (preceded by 1 blank character) „CR“

ASCII-Code (Hex.)	0x20	0x32	0x30	0x39	0x39	0x0D
Characters	SP	2	0	9	9	CR

Advices:

ASCII characters can be easily shown using a terminal program.

The output rate in ASCII format is reduced automatically by skipping individual measurement values, see Chap. 6.9.

### 8.3 Set-up of the Commands

The commands for the sensors are comprised of command data which are transmitted in full duplex mode. Each command packet is comprised of a whole number multiple of 32 bit words, see Fig. 44.

	31	24	23	16	15	8	7	0
1	Header							
2	(ID)							
3	Command (16 Bit)				Package length (16 Bit)			
4	Data 1							
5	...							
6	Data (n)							

Contents	
Start word	Command header (2 words)
Sensor identifier e.g. „ILD1“	
Command code	Data word quantity n+2
1 <sup>st</sup> Data word (4 Bytes)	
...	
n <sup>th</sup> Data word (4 Bytes)	



#### IMPORTANT!

The sensor continues to deliver measurement values to the analog output even while communicating with the sensor.

Fig. 44 Structure of a command packet

Since most serial interfaces use an 8 bit data format, 4 consecutive bytes are combined into a 32 bit word. Each command packet has a header consisting of two 32 bit words followed by the command and, if required, other data as well. The top two bits (No. 31 and 30) are always “0” in the transmitted command.

#### Example:

Command **SET\_AVX**. Sets the averaging number N for the moving and recursive average.

Command: 0x2075

Averaging number:  $N = 1024$ , therewith  $X = \log_2 1024 = 10 (= 0xA)$

Data word:  $n = 1$

Package length: 3

For further informations on this command, see Chap. 8.5.4.

Format:

31	24	23	16	15	8	7	0	hex	Contents		
„+“	„+“	„+“	„+“	„+“	„+“	„+“	„+“	0x0d („CR“)	0x2B2B2B0D	Start word	
„I“	„L“	„L“	„L“	„D“	„D“	„D“	„D“	„1“	0x494C4431	Identifier ID „ILD1“	
0x20	0x75	0x75	0x75	0x00	0x00	0x00	0x03	0x20750003	Command (0x2075) 2 top bits = 0	Package length = 3	
0x00	0x0A	0x0000000A	Data word 1 (X = 0xA)								

## 8.4 Command Reply

### 8.4.1 Communication without Error

No start word is transmitted, if the sensor replies to a command. The 1st word then is the sensor identifier. The second word is the command with set MSB (Bit 31 = 1, corresponding an OR operation of the command with 0x8000) and the new package length, if there was no error during communication. With longer answers (e.g. GET\_INFO) the package length is larger according to the quantity of data words to be transmitted. A firm 32 bit word 0x20200D0A forms the conclusion of the answer. The conclusion word is not a data word.

**Example:** Sensor reply (without error) to the SET\_AVX command.

31	24	23	16	15	8	7	0	hex	Contents		
„I“	„L“	„L“	„L“	„D“	„D“	„D“	„D“	„1“	0x494C4431	Identifier ID „ILD1“	
0xA0	0x75	0x75	0x75	0x00	0x00	0x00	0x02	0xA0750002	0x2075 OR 0x8000 (MSB = 1)	Package length (2)	
0x20	0x20	0x20	0x20	0x0D	0x0D	0x0D	0x0A	0x20200D0A	Conclusion word		

Wait until the sensor reply, before you send a new command to the sensor.

### 8.4.2 Communication with Error

If the sensor detects an error during the execution of a command, the second highest bit (bit 30) of the command is also set (the command is OR operated with 0xC000). Additionally a command error code is transferred as data word, see Fig. 45. The resulting package length amounts to now 3 data words. The reply is finished with a 32 bit word 0x20200D0A (2 blank characters + CR + LF).

Error-Code X	Description
1	Command unknown
2	Incorrect parameter value
3	Invalid parameter
4	Time out
5	Command failed
6	Warning for averaging type and averaging number <sup>1</sup>

Fig. 45 Command error codes

**Example:** Sensor operates in the average mode “Median“. The command SET\_AVX is not possible in this averaging mode and leads to the following answer.

31	24	23	16	15	8	7	0	hex	Contents
„I“	„L“	„D“	„1“					0x494C4431	Identifier ID „ILD1“
0xE0	0x73	0x00	0x03					0xE0730003	0x2075 OR 0xC000 (2 top bits = 1)      Package length = 3
0x00	0x00	0x00	0x05					0x00000005	Command error code: 5 „Command failed“
0x20	0x20	0x0D	0x0A					0x20200D0A	Conclusion word

The sensor continues to deliver measurement values to the analog output even while communicating with the sensor. The measurement value output on the digital interface is momentarily interrupted.

1) , see Chap. 8.5.5.

## 8.5 Commands

### 8.5.1 Overview



#### IMPORTANT!

Wait until the sensor reply, before you send a new command to the sensor.

<b>Information commando</b>		
0x20490002	GET_INFO	Shows sensor data
0x204A0002	GET_SETTINGS	Shows sensor settings
<b>Average</b>		
0x20700002	SET_AV0	Sets Average 0 = 1 (Median 3)
0x20710002	SET_AV1	Sets Average 1 = 4 (Median 5)
0x20720002	SET_AV2	Sets Average 2 = 32 (Median 7)
0x20730002	SET_AV3	Sets Average 3 = 128 (Median 9)
0x20750003	SET_AVX	Average X = $\log_2$ (MV)
0x207D0003	SET_AV_T	Selects average type
<b>Measurement value output</b>		
0x20770002	DAT_OUT_ON	Permanent measurement value output
0x20760002	DAT_OUT_OFF	Stops measurement value output
0x202C0003	GET_MEASVALUE	Reduced measurement value output (polling)
<b>Fixed points and limits</b>		
0x207E0007	SET_LIMITS	Sets limits, hysteresis and master
0x20830002	SET_UPPERLIMIT_F1	Assignment OG -> Limit 1
0x20840002	SET_LOWERLIMIT_F1	Assignment UGt -> Limit 1
<b>Error and measurement value outputs</b>		
0x20950003	SET_ERROROUTPUT	Error mode and switchmode for synchronization or triggering
0x20900003	SET_OUTPUTTYP	Measurement value output : Current, Voltage, RS422
<b>Speed</b>		
0x20850003	SET_SPEED	Measurement frequency: 2.5 kHz; 1.25 kHz; 625 Hz; 312.5 Hz
0x20800003	SET_BAUDRATE	Baudrate: 115.2/ 57.6/19.2/9.6 kBaud

<b>Error output (Analog output)</b>		
0x20810003	SET_ERRORHANDLER	In case of error: Keep / do not keep last valid measurement value
<b>Synchron or trigger mode</b>		
0x20820003	SET_SYNCMODE SET_TRIGGERMODE	Master / Slave, on, off, alternating; triggering
<b>Switching off the laser (external)</b>		
0x20870002	LASER_ON	Switches the laser on
0x20860002	LASER_OFF	Switches the laser off
<b>Measurement value data format</b>		
0x20880003	ASCII_OUTPUT	Options: ASCII / Binary
<b>Key lock</b>		
0x20600003	SET_KEYLOCK	Options: Keys enables or locked
<b>Reset</b>		
0x20F10002	SET_DEFAULT	Reset to default factory settings
0x20F00002	RESET_BOOT	Reboot the sensor
<b>Lock Flashwrite</b>		
0x20610003	WriteFlashZero	Lock the Flashwriting for setting masters and the mid-point
<b>Setting Masters, Setting Mid-Point</b>		
0x20660003	SET_ZERO	Start setting masters measurement respectively relative measurement

**IMPORTANT!**

If initialization has been finished, the sensor transmits the info string once in ASCII format. The initialization including the info string transmission takes up to 10 seconds. Within this period, the sensor neither executes nor replies commands.

**8.5.2 Reading out the Sensor Parameters**

Name: Get\_Info

Description: Supplies the info string. This shows all parameters currently stored in the sensor.

Format:	31	24	23	16	15	8	7	0	hex
	„+“		„+“		„+“		0x0d („CR“)		0x2B2B2B0D
	„I“		„L“		„D“		„1“		0x494C4431
	0x20		0x49		0x00		0x02		0x20490002

Reply:	31	24	23	16	15	8	7	0	hex
	„I“		„L“		„D“		„1“		0x494C4431
	0xA0		0x49		0x00		0x70		0xA0490070
Info string in the form of a readable ASCII character string:									
ILD 1700 : Standard output : RS422err frequency : 2500 Hz average-number : 1 syncmode <sup>1</sup> : M S off keylock: no range: 10 option : 0 date: 06/03/09 sw type: 0					Softwareversion : 5.005 speed : 1 average-type : moving hold value : yes ASCII-output: no Flash enable: yes serialnumber: 1234568 articlenumber : 4120088 bootloaderversion: 1.52				
	0x20		0x20		0x0D		0x0A		0x20200D0A

1) Depends on operation mode settings (synchronization or trigger). Options with synchronization: Master sync. off, master sync. on, slave, master alternating. Options with trigger: Edge LH, edge HL, level H, level L

### 8.5.3 Reading out the Sensor Settings

Name: Get\_Settings

Description: Supplies the current sensor settings

These are as follows:

**Average:** Integer in hex form of the exponents as the base 2 of the average number for the moving and recursive averaging types. For **Median:**

0 = 3

2 = 5

5 = 7

7 = 9

**Upper limit:** Integer in hex form (count value)

**Lower limit:** Integer in hex form (count value)

**Upper hysteresis value:** Integer in hex form (count value)

**Lower hysteresis value:** Integer in hex form (count value)

**Master value:** Integer in hex form (count value)

**Master and mid-point value set (M):**

0 = Not mastered in switch mode, mid-point value not set in error mode

1 = Mastered in switch mode, mid-point value not set in error mode

2 = Not mastered in switch mode, mid-point value set in error mode

3 = Mastered in switch mode, mid-point value set in error mode

**Flag for hold last value:**

0 = Do not keep last measurement value

1 = Keep last measurement value

**Assignment of the limits to the error outputs**

1 = upper limit > F1, lower limit > F2

0 = upper limit > F2, lower limit > F1

**Synchron mode <sup>1</sup>:**

0 = Master synch off

1 = Mast synch on

2 = Slave

3 = Master synch alternating

**Average type:**

0 = Recursive

1 = Moving

2 = Median

**Baud rate:**

0 = 115.200 Baud

1 = 57.600 Baud

2 = 19.200 Baud

3 = 9.600 Baud

**ASCII output**

0 = Binary format

1 = ASCII format

**Laser status**

0 = Laser off

1 = Laser on

**Trigger mode <sup>1</sup>:**

0 = Edge LH

1 = Edge HL

2 = Level high

3 = Level low

**Output type:**

0 = Current

1 = Voltage

2 = digital

**Measurement**

**speed:**

0 = 1

1 = 1/2

2 = 1/4

3 = 1/8

**Operation mode:**

0 = Sync. error

1 = Sync. switch

2 = Trigger error

3 = Trigger switch

1) Depends on operation mode settings (synchronization or trigger).

**Measurement range:**

Integer in hex form in mm

**Digital data output:**

0 = Data output switched off

1 = Data output switched on

**Key lock:**

0 = Keys enabled

1 = Keys locked

**Enable Flash:**

0 = Flashwrite locked

1 = Flashwrite enabled

Format:

31	24	23	16	15	8	7	0	hex
„+“	„+“	„+“	0x0d („CR“)					0x2B2B2B0D
„I“	„L“	„D“	„1“					0x494C4431
0x20	0x4A	0x00	0x02					0x204A0002

Reply:

31	24	23	16	15	8	7	0	hex
„I“	„L“	„D“	„1“					0x494C4431
0xA0	0x4A	0x00	0x17					0xA04A0017
<b>Output type</b>								
0x00	0x00	0x00	0x0X					0x0000000X
<b>Measurement speed</b>								
0x00	0x00	0x00	0x0X					0x0000000X
<b>Averaging number</b>								
0x00	0x00	0x00	0x0X					0x0000000X

<b>Flag hold last value</b>				
0x00	0x00	0x00	0x0X	0x0000000X
<b>Synchron mode</b>				
0x00	0x00	0x00	0x0X	0x0000000X
<b>Averaging type</b>				
0x00	0x00	0x00	0x0X	0x0000000X
<b>Operation mode</b>				
0x00	0x00	0x00	0x0X	0x0000000X
<b>Baud rate</b>				
0x00	0x00	0x00	0x0X	0x0000000X
<b>ASCII / Binary output</b>				
0x00	0x00	0x00	0x0X	0x0000000X
<b>Upper limit</b>				
0x00	0x00	0xXX	0xXX	0x0000XXXX
<b>Upper limit</b>				
0x00	0x00	0xXX	0xXX	0x0000XXXX
<b>Upper hysteresis value</b>				
0x00	0x00	0xXX	0xXX	0x0000XXXX
<b>Lower Hysteresis value</b>				
0x00	0x00	0xXX	0xXX	0x0000XXXX
<b>Master value</b>				
0x00	0x00	0xXX	0xXX	0x0000XXXX

<b>Master and mid-point value set</b>				
0x00	0x00	0x00	0x0X	0x0000000X
<b>Measuring range</b>				
0x00	0x00	0xXX	0xXX	0x0000XXXX
<b>Assignment of the limits to the switching outputs</b>				
0x00	0x00	0xXX	0xXX	0x0000XXXX
<b>Key lock</b>				
0x00	0x00	0x00	0x0X	0x0000000X
<b>Data output digital</b>				
0x00	0x00	0x00	0x0X	0x0000000X
<b>Laser status</b>				
0x00	0x00	0x00	0x0X	0x0000000X
0x20	0x20	0x0D	0x0A	0x20200D0A
<b>Enable Flash</b>				
0x00	0x00	0x0X	0x0X	0x0000000X
0x20	0x20	0x0A	0x0A	0x20200D0A

**IMPORTANT!**

The “avg” LED shows the current status after the command SET\_AVO...3 on.

**8.5.4 Set Average Number**

Name: SET\_AVO

Description: Sets the averaging number to 1 for moving and recursive averages, and to 3 for median.

Format:	31	24	23	16	15	8	7	0	hex
	„+“		„+“		„+“		0x0d („CR“)		0x2B2B2B0D
	„I“		„L“		„D“		„1“		0x494C4431
	0x20		0x70		0x00		0x02		0x20700002

Reply:	31	24	23	16	15	8	7	0	hex
	„I“		„L“		„D“		„1“		0x494C4431
	0xA0		0x70		0x00		0x02		0xA0700002
	0x20		0x20		0x0D		0x0A		0x20200D0A

Name: SET\_AV1

Description: Sets the averaging number to 4 for moving and recursive averages, and to 5 for median.

Format:	31	24	23	16	15	8	7	0	hex
	„+“		„+“		„+“		0x0d („CR“)		0x2B2B2B0D
	„I“		„L“		„D“		„1“		0x494C4431
	0x20		0x71		0x00		0x02		0x207130002

Reply:	31	24	23	16	15	8	7	0	hex
	„I“		„L“		„D“		„1“		0x494C4431
	0xA0		0x71		0x00		0x02		0xA0710002
	0x20		0x20		0x0D		0x0A		0x20200D0A

Name: SET\_AV2

Description: Sets the averaging number to 32 for moving and recursive averages, and to 7 for median.

Format:	31	24	23	16	15	8	7	0	hex
	„+“		„+“		„+“		0x0d („CR“)		0x2B2B2B0D
	„I“		„L“		„D“		„1“		0x494C4431
	0x20		0x72		0x00		0x02		0x20720002

Reply:	31	24	23	16	15	8	7	0	hex
	„I“		„L“		„D“		„1“		0x494C4431
	0xA0		0x72		0x00		0x02		0xA0720002
	0x20		0x20		0x0D		0x0A		0x20200D0A

Name: SET\_AV3

Description: Sets the averaging number to 128 for moving and recursive averages, and to 9 for median.

Format:	31	24	23	16	15	8	7	0	hex
	„+“		„+“		„+“		0x0d („CR“)		0x2B2B2B0D
	„I“		„L“		„D“		„1“		0x494C4431
	0x20		0x73		0x00		0x02		0x20730002

Reply:	31	24	23	16	15	8	7	0	hex
	„I“		„L“		„D“		„1“		0x494C4431
	0xA0		0x73		0x00		0x02		0xA0730002
	0x20		0x20		0x0D		0x0A		0x20200D0A

**IMPORTANT!**

SET\_AVX is not available for the **median!**

The maximum value for N for the moving average is 128.

**Note:** The "avg" LED goes off after SET\_AVX.

Name: SET\_AVX

Description: Sets the averaging number N for the moving and recursive averages to  $N=2^X$ . Value range for X : 0...15 (0x00...0x0F). This command is not available for the median. If attempted, the sensor issues the message „Command failed“.

Format:	31	24	23	16	15	8	7	0	hex
	„+“		„+“		„+“		0x0d („CR“)		0x2B2B2B0D
	„I“		„L“		„D“		„1“		0x494C4431
	0x20		0x75		0x00		0x03		0x20750003
	0x00		0x00		0x00		0x0X		0x0000000X

Reply:	31	24	23	16	15	8	7	0	hex
	„I“		„L“		„D“		„1“		0x494C4431
	0xA0		0x75		0x00		0x02		0xA0750002
	0x20		0x20		0x0D		0x0A		0x20200D0A

**X =  $\log_2(N)$**  N = averaging number

This results in the following values for the averaging number N:

N	1	2	4	8	16	32	64	128	256	512	1024	2048	4096	8192	16384	32768
X	0	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15

Advice: If the existing averaging number is higher than that permitted for the new averaging type, the averaging number will be set to the upper limit for the new average type.

Overview:	Command	Averaging number N		
		recursive average	moving average	Median
	SET_AV 0...3	1, 4, 32, 128	1, 4, 32, 128	3, 5, 7, 9
	SET_AVX	1 ... 32767	1 ... 128	Command failed

Example:

Average 8  $X = \log_2(8) = 3$

Average 512  $X = \log_2(512) = 9$

### 8.5.5 Set Average Type

Name: SET\_AV\_T

Description: Sets the type of average.

Options:

- moving average for 1 to 128 measurement values
- Recursive average for 1 to 32768 measurement values
- Median for 3, 5, 7 or 9 measurement values

Format:	31	24	23	16	15	8	7	0	hex
	„+“		„+“		„+“		0x0d („CR“)		0x2B2B2B0D
	„ “		„L“		„D“		„1“		0x494C4431
	0x20		0x7D		0x00		0x03		0x207D0003
	0x00		0x00		0x00		0x0X		0x0000000X
Reply:	31	24	23	16	15	8	7	0	hex
	„ “		„L“		„D“		„1“		0x494C4431
	0xA0		0x7D		0x00		0x02		0xA07D0002
	0x20		0x20		0x0D		0x0A		0x20200D0A

Parameter:

- X = 0 --> recursive average
- X = 1 --> recursive average
- X = 2 --> Median

### 8.5.6 Starting and Stopping the Measurement Value Output

Start command

Name: DAT\_OUT\_ON

Description: Switches on the digital data output for the measurement values. The output channel (output type) must also be set to the digital output, otherwise the measurement data cannot be received by the sensor.

Format:	31	24	23	16	15	8	7	0	hex
	„+“		„+“		„+“		0x0d („CR“)		0x2B2B2B0D
	„I“		„L“		„D“		„1“		0x494C4431
	0x20		0x77		0x00		0x02		0x20770002

Reply:	31	24	23	16	15	8	7	0	hex
	„I“		„L“		„D“		„1“		0x494C4431
	0xA0		0x77		0x00		0x02		0xA0770002
	0x20		0x20		0x0D		0x0A		0x20200D0A

Stop command

Name: DAT\_OUT\_OFF

Description: Switches off the digital output for the measurement values. This has no effect on communication with the sensor via the digital interface. This command has a higher priority than GET\_MEASVALUE in trigger mode.

Format:	31	24	23	16	15	8	7	0	hex
	„+“		„+“		„+“		0x0d („CR“)		0x2B2B2B0D
	„I“		„L“		„D“		„1“		0x494C4431
	0x20		0x76		0x00		0x02		0x20760002

**Advice:** The sensor sends digital measurement values again when the operating voltage has been switched on again.



#### IMPORTANT!

The STOP command is volatile and is lost if the power supply is switched off or the RESET\_BOOT command is sent.

Reply:

31	24	23	16	15	8	7	0	hex
„I“		„L“		„D“		„1“		0x494C4431
0xA0		0x76		0x00		0x02		0xA0760002
0x20		0x20		0x0D		0x0A		0x20200D0A

### 8.5.7 Set Limit Values

Name: SET\_LIMITS

Description: Sets limits and hysteresis values in the operation mode „Sync. switch mode“ respectively „Trigger switch mode“ (upper/lower limit, upper/lower hysteresis value).

31	24	23	16	15	8	7	0	hex
„+“		„+“		„+“		0x0d („CR“)		0x2B2B2B0D
„I“		„L“		„D“		„1“		0x494C4431
0x20		0x7E		0x00		0x07		0x207E0007
<b>Upper limit value</b>								
0x00		0x00		0xXX		0xXX		0x0000XXXX
<b>Lower limit value</b>								
0x00		0x00		0xXX		0xXX		0x0000XXXX
<b>Upper hysteresis value</b>								
0x00		0x00		0xXX		0xXX		0x0000XXXX
<b>Lower hysteresis value</b>								
0x00		0x00		0xXX		0xXX		0x0000XXXX
<b>Master value</b>								
0x00		0x00		0xXX		0xXX		0x0000XXXX

**Note:** The hysteresis values have the effect of resetting the assigned switch outputs when the measurement values return to the target range.

Reply:	31	24	23	16	15	8	7	0	hex
	„I“		„L“		„D“		„1“		0x494C4431
	0xA0		0x7E		0x00		0x02		0xA07E0002
	0x20		0x20		0x0D		0x0A		0x20200D0A

Note: All values are absolute values; Input as an integer value (whole number count value) of 2 bytes, completed by two advance bytes with the value "0" to a total length of 32 bits.

### 8.5.8 Assignment of the Limits to the Switch Outputs

Name: SET\_UPPERLIMIT\_F1

Description: Assigns the upper limit to switching output 1 and the lower limit to switching output 2.

Standard setting:  
Switching output 1  
Upper limit,

Format:	31	24	23	16	15	8	7	0	hex
	„+“		„+“		„+“		0x0d („CR“)		0x2B2B2B0D
	„I“		„L“		„D“		„1“		0x494C4431
	0x20		0x83		0x00		0x02		0x20830002

Switching output 2  
Lower limit

Reply:	31	24	23	16	15	8	7	0	hex
	„I“		„L“		„D“		„1“		0x494C4431
	0xA0		0x83		0x00		0x02		0xA0830002
	0x20		0x20		0x0D		0x0A		0x20200D0A

Name: SET\_LOWERLIMIT\_F1

Description: Assigns the upper limit to switching output 2 and the lower limit to switching output 1.

Format:	31	24	23	16	15	8	7	0	hex
	„+“		„+“		„+“		0x0d („CR“)		0x2B2B2B0D
	„I“		„L“		„D“		„1“		0x494C4431
	0x20		0x84		0x00		0x02		0x20840002

Reply:	31	24	23	16	15	8	7	0	hex
	„I“		„L“		„D“		„1“		0x494C4431
	0xA0		0x84		0x00		0x02		0xA0840002
	0x20		0x20		0x0D		0x0A		0x20200D0A

### 8.5.9 Operation Mode

Name: SET\_ERROROUTPUT

Description: Sets the use on synchron mode or trigger mode. Both modes exclude each other as the input lines are used for synchronisation or triggering. Additionally the use of the switching outputs is set. In error mode, switching output 1 is used as the error output. In switch mode, both outputs are used as limit outputs.

Standard setting:

Sync error

Options:

X = 0 > Ssync error

X = 1 > Ssync switch

X = 2 > Trigger error

X = 3 > Trigger switch

Format:	31	24	23	16	15	8	7	0	hex
	„+“		„+“		„+“		0x0d („CR“)		0x2B2B2B0D
	„I“		„L“		„D“		„1“		0x494C4431
	0x20		0x95		0x00		0x03		0x20950003
	0x00		0x00		0x00		0x0X		0x0000000X

Reply:	31	24	23	16	15	8	7	0	hex
	„I“		„L“		„D“		„1“		0x494C4431
	0xA0		0x95		0x00		0x02		0xA0950002
	0x20		0x20		0x0D		0x0A		0x20200D0A

**8.5.10 Set the Measurement Value Output Type**

Name: SET\_OUTPUTTYP

Description: Sets the output type for the measurement values.

Options:  
X = 0 > Current  
(4..20 mA)

Format:	31	24	23	16	15	8	7	0	hex
	„+“		„+“		„+“		0x0d („CR“)		0x2B2B2B0D
	„I“		„L“		„D“		„1“		0x494C4431
	0x20		0x90		0x00		0x03		0x20900003
	0x00		0x00		0x00		0x0X		0x0000000X

X = 1 > Voltage  
(0..10 V)

X = 2 &gt; RS422

Reply:	31	24	23	16	15	8	7	0	hex
	„I“		„L“		„D“		„1“		0x494C4431
	0xA0		0x90		0x00		0x02		0xA0900002
	0x20		0x20		0x0D		0x0A		0x20200D0A

**8.5.11 Set Measurement Frequency (Speed)**

Name: SET\_SPEED

Description: Sets the measurement frequency

Options:  
X = 0 > 2.5 kHz  
X = 1 > 1.25 kHz  
X = 2 > 625 Hz  
X = 3 > 312.5 Hz

Format:	31	24	23	16	15	8	7	0	hex
	„+“		„+“		„+“		0x0d („CR“)		0x2B2B2B0D
	„I“		„L“		„D“		„1“		0x494C4431
	0x20		0x85		0x00		0x03		0x20850003
	0x00		0x00		0x00		0x0X		0x0000000X

Reply:	31	24	23	16	15	8	7	0	hex
	„I“		„L“		„D“		„1“		0x494C4431
	0xA0		0x85		0x00		0x02		0xA0850002
	0x20		0x20		0x0D		0x0A		0x20200D0A

Name: SET\_BAUDRATE

Description: Sets the transmission rate

Options:

X = 0 > 115200 Baud

X = 1 > 57600 Baud

X = 2 > 19200 Baud

X = 3 > 9600 Baud

Format:	31	24	23	16	15	8	7	0	hex
	„+“		„+“		„+“		0x0d („CR“)		0x2B2B2B0D
	„I“		„L“		„D“		„1“		0x494C4431
	0x20		0x80		0x00		0x03		0x20800003
	0x00		0x00		0x00		0x0X		0x0000000X

Reply:	31	24	23	16	15	8	7	0	hex
	„I“		„L“		„D“		„1“		0x494C4431
	0xA0		0x80		0x00		0x02		0xA0800002
	0x20		0x20		0x0D		0x0A		0x20200D0A

The sensor still sends the reply with the old baud rate and only switches to the new baud rate once the reply has been sent. The output rate reduces automatically when the baud rate is changed because individual measurement values are skipped.

### 8.5.12 Error Output (Analog Output)

Name: SET\_ERRORHANDLER

Description: Switches on the flag for keep / do not keep the last measurement value

This flag only affects the analog output. If set to X = 1 the last valid measurement value will continue to be issued if an error occurs (no object, invalid object, object outside the measurement range or laser turned off). If set to X = 0 an error signal will be generated for the current output that has an error value of 3 mA and for the voltage output that has a value of 10.2 V.

Options:

X = 0 > Do not hold the last value

X = 1 > Hold last value

Format:	31	24	23	16	15	8	7	0	hex
	„+“		„+“		„+“		0x0d („CR“)		0x2B2B2B0D
	„I“		„L“		„D“		„1“		0x494C4431
	0x20		0x81		0x00		0x03		0x20810003
	0x00		0x00		0x00		0x0X		0x0000000X

Reply:	31	24	23	16	15	8	7	0	hex
	„I“		„L“		„D“		„1“		0x494C4431
	0xA0		0x81		0x00		0x02		0xA0810002
	0x20		0x20		0x0D		0x0A		0x20200D0A

### 8.5.13 Synchronous and Trigger Mode

Options:

X = 0 &gt; Synchronous master off

X = 1 &gt; Synchronous master on

X = 2 &gt; Slave

X = 3 &gt; Alternating synchronous master

Name: SET\_SYNCMODE/TRIGGERMODE

**Synchron mode:** This command can be used for synchronizing two (or more) sensors with each other. One sensor functions as the master, the other as the slave. Master and Slave alternately measure in alternating mode to avoid interference of each other when measuring on transparent objects.

Advice: The same measurement frequency (speed) must be set for the master and the slave, otherwise there is a risk of unreliable measurements.

**Trigger mode:** The synchron lines are used as trigger inputs. Four trigger types are available:

Format:	31	24	23	16	15	8	7	0	hex
	„+“		„+“		„+“		0x0d („CR“)		0x2B2B2B0D
	„I“		„L“		„D“		„1“		0x494C4431
	0x20		0x82		0x00		0x03		0x20820003
	0x00		0x00		0x00		0x0X		0x0000000X

Reply:	31	24	23	16	15	8	7	0	hex
	„I“		„L“		„D“		„1“		0x494C4431
	0xA0		0x82		0x00		0x02		0xA0820002
	0x20		0x20		0x0D		0x0A		0x20200D0A

Options:

X = 0 &gt; edge LH,

X = 1 &gt; edge HL,

X = 2 &gt; level high,

X = 3 &gt; level low.

**8.5.14 Switching off the Laser (External)**

Name: LASER\_OFF

Description: Switches off the laser.

**IMPORTANT!**

The command LASER\_OFF is volatile. This means that the laser is switched on again if the power supply was switched off or the sensor was rebooted by means of the RESET\_BOOT command and pin 9 is connected with GND.

Format:	31	24	23	16	15	8	7	0	hex
	„+“		„+“		„+“		0x0d („CR“)		0x2B2B2B0D
	„I“		„L“		„D“		„1“		0x494C4431
	0x20		0x86		0x00		0x02		0x20860002

Reply:	31	24	23	16	15	8	7	0	hex
	„I“		„L“		„D“		„1“		0x494C4431
	0xA0		0x86		0x00		0x02		0xA0860002
	0x20		0x20		0x0D		0x0A		0x20200D0A

Name: LASER\_ON

Description: Switches the laser on

Format:	31	24	23	16	15	8	7	0	hex
	„+“		„+“		„+“		0x0d („CR“)		0x2B2B2B0D
	„I“		„L“		„D“		„1“		0x494C4431
	0x20		0x87		0x00		0x02		0x20870002

Reply:	31	24	23	16	15	8	7	0	hex
	„I“		„L“		„D“		„1“		0x494C4431
	0xA0		0x87		0x00		0x02		0xA0870002
	0x20		0x20		0x0D		0x0A		0x20200D0A

The command LASER\_ON is effective only if pin 9 is connected with GND.

**8.5.15 Switching the Data Format**

Name: ASCII\_OUTPUT

Description: Switches the data format for the measurement value output via the digital interface.

Format:	31	24	23	16	15	8	7	0	hex
	„+“		„+“		„+“		0x0d („CR“)		0x2B2B2B0D
	„l“		„L“		„D“		„1“		0x494C4431
	0x20		0x88		0x00		0x02		0x20880002
	0x00		0x00		0x00		0x0X		0x0000000X

Reply:	31	24	23	16	15	8	7	0	hex
	„l“		„L“		„D“		„1“		0x494C4431
	0xA0		0x88		0x00		0x02		0xA0880002
	0x20		0x20		0x0D		0x0A		0x20200D0A

Options:

X = 0 &gt; Binary output (2 Byte)

X = 1 &gt; ASCII output (6 Byte)

**8.5.16 Key Lock**

Name: SET\_KEYLOCK

Description: Locks or enables the membrane keys. The set status is not volatile.

Options:

X = 0 &gt; Enable keys

X = 1 &gt; Lock keys

Format:	31	24	23	16	15	8	7	0	hex
	„+“		„+“		„+“		0x0d („CR“)		0x2B2B2B0D
	„ “		„L“		„D“		„1“		0x494C4431
	0x20		0x60		0x00		0x03		0x20600003
	0x00		0x00		0x00		0x0X		0x0000000X

Reply:	31	24	23	16	15	8	7	0	hex
	„ “		„L“		„D“		„1“		0x494C4431
	0xA0		0x60		0x00		0x02		0xA0600002
	0x20		0x20		0x0D		0x0A		0x20200D0A

**8.5.17 Set Factory Setting**

Name: SET\_DEFAULT

Description: Resets the set parameters to the default settings (factory settings).

This concerns:

- Output type (current)
- Measurement frequency
- Averaging number (1)
- Hold last measurement value,
- Synchronization (no synchronization),
- Averaging type (moving),
- Operation mode (sync error),
- Baud rate (115200 baud),
- Binary output,
- Laser (on),
- Data output (on),
- Assignment of the switching outputs (upper limit > F1, lower limit > F2),
- Default values for master, offset, limit and hysteresis values
- Keys enabled
- Flash enabled

Format:	31	24	23	16	15	8	7	0	hex
	„+“		„+“		„+“		0x0d („CR“)		0x2B2B2B0D
	„I“		„L“		„D“		„1“		0x494C4431
	0x20		0xF1		0x00		0x02		0x20F10002
Reply:	31	24	23	16	15	8	7	0	hex
	„I“		„L“		„D“		„1“		0x494C4431
	0xA0		0xF1		0x00		0x02		0xA0F10002
	0x20		0x20		0x0D		0x0A		0x20200D0A

### 8.5.18 Reset Sensor

Name: RESET\_BOOT

Description: Starts the sensor's initialization phase. The set parameters are retained. The short-circuit protection for the switch outputs is also reset in the process.

#### IMPORTANT!

The volatile commands Laser\_off and DAT\_UT\_OFF are lost after the RESET command.

This means that the laser is switched on again and the sensor sends measurement values again.

Format:	31	24	23	16	15	8	7	0	hex
	„+“		„+“		„+“		0x0d („CR“)		0x2B2B2B0D
	„I“		„L“		„D“		„1“		0x494C4431
	0x20		0xF0		0x00		0x02		0x20F00002
Reply:	31	24	23	16	15	8	7	0	hex
	„I“		„L“		„D“		„1“		0x494C4431
	0xA0		0xF0		0x00		0x02		0xA0F00002
	0x20		0x20		0x0D		0x0A		0x20200D0A

### 8.5.19 Reading out the Measurements

Name: GET\_MEASVALUE

Description: The command is used for polling measurements in trigger mode. The amount of measurements which the sensor should supply must be specified in the parameter. The command DAT\_OUT\_OFF resets the amount of possible measurements to be transferred to 0.

Format:

31	24	23	16	15	8	7	0	hex
„+“	„+“	„+“	„+“	„+“	„+“	„+“	0x0d („CR“)	0x2B2B2B0D
„ “	„L“	„L“	„L“	„L“	„L“	„L“	„1“	0x494C4431
0x20	0x2C	0x2C	0x00	0x00	0x00	0x03	0x03	0x202C0003
0xXX	0XXXXXXXXX							

Measurements are output in binary, see Chap. 8.2.1 or ASCII format, see Chap. 8.2.2, in trigger mode.

Reply:

31	24	23	16	15	8	7	0	hex
„ “	„L“	„L“	„L“	„L“	„L“	„L“	„1“	0x494C4431
0xE0	0x2C	0x2C	0x00	0x00	0x00	0x03	0x03	0xE02C0003
0x00	0x00	0x00	0x00	0x00	0x00	0x05	0x05	0x00000005
0x20	0x20	0x20	0x0D	0x0D	0x0D	0x0A	0x0A	0x20200D0A

**8.5.20 Enable / Lock the Flash for Setting Masters and the Mid-point**

Name: WriteFlashZero

Description: This command enables or locks saving the master values into the flash.

Parameter:

X = parameter value ( 0; 1 )      0 = lock Flash    1 = enable Flash

Format:	31	24	23	16	15	8	7	0	hex
	„+“		„+“		„+“		0x0d („CR“)		0x2B2B2B0D
	„I“		„L“		„D“		„1“		0x494C4431
	0x20		0x61		0x00		0x03		0x20610003
	0x00		0x00		0x00		0x0X		0x0000000X

The factory setting:  
“Flash enabled“

Reply:	31	24	23	16	15	8	7	0	hex
	„I“		„L“		„D“		„1“		0x494C4431
	0xA0		0x61		0x00		0x02		0xA0610002

**Advices:**

The command WriteFlashZero should be used by applications, which set before every measuring process mastering and mid-point automatically through the external input line, see Chap. 6.7, see Chap. 6.8. It will do, that the command “Lock Flash“ will be sent once.

The values for master and mid-point are saved at “Lock Flash“ only in the RAM of the sensor and get lost by switching-off the sensor. When switching-on the before saved master and mid-point values or the factory setting, see Chap. 15.4, are loaded. The command “WriteFlashZero“ itself is non-volatile. The setup “Lock Flash“ also survive after switching-off.

The command “WriteFlashZero“ only influences the setting masters and mid-point. All the others flash operations were applied as before.

### 8.5.21 Mastering or Setting Mid-point

Name: Set\_Zero

Description: The command "SetZero" enables to

- set the sensor to mid-point in the operation mode "Error-Mode" or
- mastering the sensor in the operation mode "Switch-Mode"

For sensors with software versions prior to 6,000 mid-point setting and mastering is possible with the sensor button "select/zero" or the digital "Zero" input.

Parameter X:

0 = Undo set mid-point or mastering

1 = Set mid-point or mastering

Format:	31	24	23	16	15	8	7	0	hex
	„+“		„+“		„+“		0x0D		0x2B2B2B0D
	„I“		„L“		„D“		„1“		0x494c4431
	0x20		0x66		0x00		0x03		0x20660003
	0x00		0x00		0x00		0x0X		0x0000000X

Reply, no error:	31	24	23	16	15	8	7	0	hex
	„I“		„L“		„D“		„1“		0x494C4431
	0xA0		0x66		0x00		0x02		0xA0660002
	0x20		0x20		0x0D		0x0A		0x20200D0A

Reply, with er- ror:	31	24	23	16	15	8	7	0	hex
	„I“		„L“		„D“		„1“		0x494C4431
	0xE0		0x66		0x00		0x03		0xA0660002
	0x00		0x00		0x00		0x0X		0x0000000X
	0x20		0x20		0x0D		0x0A		0x20200D0A

Error code X: Detailed information, see Chap. [8.4.2](#).

Example: X = 5 ("Command failed"), e.g. if no target is within the sensor measuring range.


Notes from version 6,000:

- With version 6,000 you can set the serial output (RS422 interface) to mid-point in the operation mode "Error-Mode" (Sync/error or Trigger/error). Mid-point means to set the analog or digital output on mid-range, see Chap. 7..
- If you use the digital input "Zero" for mid-point setting or mastering, you need no long pulse to undo it before you do mid-point setting or mastering again. With each short pulse (0.5 ... 3 s) mid-point setting or mastering is done always again. This also applies to the command Set\_Zero with the parameter value = 1.

## 9. Instruction for Operating

### 9.1 Reflection Factor of the Target Surface

In principle the sensor evaluates the diffuse part of the reflected laser light, see [Fig. 46](#).



*Fig. 46 Reflection factor of the target surface*

A statement concerning a minimum reflectance is difficult to make, because even a small diffuse fraction can be evaluated from highly reflecting surfaces. This is done by determining the intensity of the diffuse reflection from the CCD array signal in real time and subsequent compensation for intensity fluctuations, see [Chap. 3.2](#).

Dark or shiny objects being measured, e.g. black rubber, may require longer exposure times. The exposure time is dependent on the measurement frequency and can only be increased by reducing the sensor's measurement frequency.

## **9.2 Error Influences**

### **9.2.1 Light from other Sources**

Thanks to their integrated optical interference filters the optoNCDT1700 sensors offer outstanding performance in suppressing light from other sources. However, this does not preclude the possibility of interference from other light sources if the objects being measured are shiny and if lower measurement frequencies are selected. Should this be the case it is recommended that suitable shields be used to screen the other light sources. This applies in particular to measurement work performed in close proximity to welding equipment.

### **9.2.2 Color Differences**

Because of intensity compensation, color difference of targets affect the measuring result only slightly. However, such color differences are often combined with different penetration depths of the laser light into the material. Different penetration depths then result in apparent changes of the measuring spot size. Therefore color differences in combination with changes of penetration depth may lead to measuring errors.

### **9.2.3 Temperature Influences**

When the sensor is commissioned a warm-up time of at least 20 minutes is required to achieve uniform temperature distribution in the sensor. If measurement is performed in the micron accuracy range, the effect of temperature fluctuations on the sensor holder must be considered. Due to the damping effect of the heat capacity of the sensor sudden temperature changes are only measured with delay.

### **9.2.4 Mechanical Vibration**

If the sensor should be used for resolutions in the  $\mu\text{m}$  to sub- $\mu\text{m}$  range, special care must be taken to ensure stable and vibration-free mounting of sensor and target.

### **9.2.5 Movement Blurs**

If the objects being measured are fast moving and the measurement frequency is low it is possible that movement blurs may result. Always select a high measurement frequency for high-speed operations, therefore, in order to prevent errors.

### 9.2.6 Surface Roughness

In case of traversing measurements surface roughnesses of  $5\ \mu\text{m}$  and more lead to an apparent distance change (also-called surface noise). However, they can be dampened by averaging, see Chap. 6.6.

### 9.2.7 Sensor Tilting

Tilt angles of the sensor in diffuse reflection both around the X and the Y axes of less than  $5^\circ$  only have a disturbing effect with surfaces which are highly reflecting. Tilt angles between  $5^\circ$  and  $15^\circ$  lead to an apparent distance change of approximately 0.12 ... 0.2 % of the measuring range, see Fig. 47.

Tilt angles between  $15^\circ$  and  $30^\circ$  lead to an apparent distance change of approximately 0.5 % of the measuring range. These influences must be considered especially when scanning structured surfaces. In principle the angle behavior in triangulation also depends on the reflectivity of the target.





Fig. 47 Angle influences

Angle	X-axis %	Y-axis %
$\pm 5^\circ$	typ. 0.12	typ. 0.12
$\pm 15^\circ$	typ. 0.2	typ. 0.2
$\pm 30^\circ$	typ. 0.5	typ. 0.5


Fig. 48 Measurement errors through tilting with diffuse reflection

### 9.3 Optimizing the Measuring Accuracy



In case of rolled or polished metals that are moved past the sensor the sensor plane must be arranged in the direction of the rolling or rinding marks. The same arrangement must be used for color strips, see [Fig. 49](#).

*Fig. 49 Sensor arrangement in case of ground or striped surfaces*



In case of bore holes, blind holes, and edges in the surface of moving targets the sensor must be arranged in such a way that the edges do not obscure the laser spot, see [Fig. 50](#).

*Fig. 50 Sensor arrangement for holes and ridges*

## 9.4 Protective Housing

### Model types:

- SGH size S  
SGH size M:  
without air purging (with inlet and exhaust for cooling) and
- SGHF size S  
SGHF size M:  
with air purging.

The protective housing are designed to be used especially if the sensor operates in a dirty environment or higher ambient temperature. It is available as an accessory. If these protective housings are used, the linearity of the sensors in the complete system may deteriorate. For the sole purpose of protection against mechanical damage a simple protective shield with sufficiently large opening is therefore more advantageous. Installation of the sensors in the protective housings should be performed by the manufacturer, because especially in case of short reference distances the protective window must be included in the calibration.

### The following guidelines must be observed if the sensors are operated in a protective housing:

- The maximum ambient temperature within the protective housing is 45 °C.
- The requirements for compressed-air are:
  - Temperature at the inlet < 25 °C
  - The compressed-air must be free of oil and water residues. It is recommended to use two oil separators in series arrangement.
- With a flow rate for example 240 l/min ( $2.5 \cdot 10^5$  Pa) the maximum outside temperature is 65 °C.
- For higher ambient temperatures it is recommended to use an additional water-cooled carrier and cover plates outside the protective housing.
- No direct heat radiation (including sunlight!) on the protective housing. In case of direct heat radiation additional thermal protective shields must be installed.
- It is recommended that the protective window is cleaned from time to time with a soft alcohol-soaked cloth or cotton pad.

### IMPORTANT!

The protection class is limited to water (no penetrating liquids or similar)!

### The delivery includes:

The rotatable plug-nipple glands type LCKN-1/8-PK-6 (FESTO) for the compressed-air tubes with a inner diameter of 6 mm, the air plate (SGHF) and the sensor fastening accessories are included in the delivery of the protective housing.

**SGH/SGHF size S**

Dimension in mm (inches), not to scale





Fig. 51 Protective housing for measuring ranges 10/20/50/100/200/250 mm

**SGH/SGHF size M**

Dimensions in mm  
(inches), not to scale





Fig. 52 Protective housing for measuring ranges 40/500/750 mm

## 10. ILD1700 Tool

The software ILD1700 Tool

- transfers and reads sensor parameters and
- reads and displays measuring results in a diagram.

All data are transmitted through a RS422 interface and can be saved on demand.

**i** Disconnect or connect the D-sub connection between RS422 and USB converter when the sensor is disconnected from power supply only.

### 10.1 Installation and Preparation for Measurements

#### 10.1.1 System Requirements

The following system requirements are recommended:


- Windows 2000, Windows XP or Windows 7 / Pentium III  $\geq$  1 GHz / 1 GB RAM
- Free USB port or IF2008

#### 10.1.2 Cable and Program Routine Requirements

- PC1700-x/USB/IND Sensor cable with RS422-USB converter and 24 V power supply
- ILD1700 Tool Configuration and measurement program
- RS422/USB converter, inclusive CD with driver

PC1700-x/USB/IND	
Pin	Signal
1	RX -
2	Rx+
3	TX+
4	TX -
5	GND

Pin assignment,  
9-pol. D SUB




*Fig. 53 Setup of the system for the demonstration software*

You will find the actual drivers respectively program routines under:

[www.micro-epsilon.com/link/opto/1700](http://www.micro-epsilon.com/link/opto/1700)

You will find details to the driver installation in the mounting instructions „Converter RS422 to USB“.

## 10.2 Measurement



i If the sensor's analog output is to be used after termination of the ILD1700 tool, it previously has to be defined as output version. Do not forget to save the settings made.

Fig. 54 Start screen of the measurement program

This sub program can be used to acquire, evaluate and store data from an ILD1700 sensor.

## 11. Software Support with MEDAQLib

The Micro-Epsilon Data Acquisition Library offers you a high level interface library to access optoNCDT laser sensors from your Windows application in combination with

- RS422/USB converter (optional accessory) and a suitable PC1700-x/USB/IND cable or
- IF2008 PCI interface card and PC1700-x/IF2008 cable

into an existing or a customized PC software.

You need no knowledge about the sensor protocol to communicate with the individual sensors. The individual commands and parameters for the sensor to be addressed will be set with abstract functions.

MEDAQLib translates the abstract functions in comprehensible instructions for the sensor.

MEDAQLib

- is a DLL/LIB usable for C, C++, VB, Delphi and many other Windows programming languages,
- supports functions to talk to the sensor
- hides the details on how to talk to the communication interface (RS232,RS422,USB,TCP)
- hides the details of the sensor protocol
- converts the incoming data to „expected data values“
- provides a consistent programming interface for all Micro-Epsilon sensors
- provides many programming examples many different programming languages
- the interface is documented in a large \*.pdf file

You will find the latest MEDAQLib version at:

[www.micro-epsilon.com/download](http://www.micro-epsilon.com/download)

[www.micro-epsilon.com/link/software/medaqlib](http://www.micro-epsilon.com/link/software/medaqlib)

## 12. Warranty

All components of the device have been checked and tested for perfect function in the factory. In the unlikely event that errors should occur despite our thorough quality control, this should be reported immediately to MICRO-EPSILON.

The warranty period lasts 12 months following the day of shipment. Defective parts, except wear parts, will be repaired or replaced free of charge within this period if you return the device free of cost to MICRO-EPSILON. This warranty does not apply to damage resulting from abuse of the equipment and devices, from forceful handling or installation of the devices or from repair or modifications performed by third parties.

No other claims, except as warranted, are accepted. The terms of the purchasing contract apply in full. MICRO-EPSILON will specifically not be responsible for eventual consequential damages. MICRO-EPSILON always strives to supply the customers with the finest and most advanced equipment. Development and refinement is therefore performed continuously and the right to design changes without prior notice is accordingly reserved. For translations in other languages, the data and statements in the German language operation manual are to be taken as authoritative.

## 13. Service, Repair

In the event of a defect on the sensor or the sensor cable:

- If possible, save the current sensor settings in a parameter set, see ILD1700 Tool, Measurement / Configuration menu, in order to load the settings back again into the sensor after the repair.
- Please send us the effected parts for repair or exchange.

In the case of faults the cause of which is not clearly identifiable, the whole measuring system must be sent back to:

MICRO-EPSILON Optronic GmbH  
Lessingstraße 14  
01465 Langebrück / Germany

Tel. +49 (0) 35201 / 729-0  
Fax +49 (0) 35201 / 729-90  
optronic@micro-epsilon.de  
www.micro-epsilon.com

## 14. Decommissioning, Disposal


- Disconnect the power supply and output cable on the sensor.
- The optoNCDT1700 is produced according to the directive 2011/65/EU "RoHS". The disposal is done according to the legal regulations (see directive 2002/96/EC).

## 15. Appendix

### 15.1 Output Rate optoNCDT1700

		Baud rate	115200	57600	19200	9600		
Measurement frequency	LED speed	Bytes	Synchron mode: Master on, Slave synchronized, Master off					
2.5 kHz	1	2	2500	2500	833.33	416.66	Binary output	
1.25 kHz	1/2	2	1250	1250	625	416.66		
625 Hz	1/4	2	625	625	625	312.5		
312.5 Hz	1/8	2	312.5	312.5	312.5	312.5		
2.5 kHz	1	6	1250	833.33	277.77	138.88	ASCII output	
1.25 kHz	1/2	6	1250	625	250	138.88		
625 Hz	1/4	6	625	625	208.33	125		
312.5 Hz	1/8	6	312.5	312.5	156.25	104.16		
			Synchron mode: Master alternating, Slave synchronized (alternating)					
2.5 kHz	1	2	1250	1250	625	416.66	Binary output	
1.25 kHz	1/2	2	625	625	625	312.5		
625 Hz	1/4	2	312.5	312.5	312.5	312.5		
312.5 Hz	1/8	2	156.25	156.25	156.25	156.25		
2.5 kHz	1	6	1250	625	250	138.88	ASCII output	
1.25 kHz	1/2	6	625	625	208.33	125		
625 Hz	1/4	6	312.5	312.5	156.25	104.16		
312.5 Hz	1/8	6	156.25	156.25	156.25	78.12		

## 15.2 Pin Assignment Sensor Cable



View: Solder-pin side male cable connector, insulator

Pin	Designation	Characteristics	Color Sensor Cable
			PC1700-x
5	+U <sub>B</sub>	Power supply (11 ... 30 VDC)	red
6	GND	System ground for power supply switch signals (Laser on/off, Mid-point, Limits)	black
13	Analog output	Current 4 ... 20 mA or Voltage 0 ... 10 V	Coaxial inner conductor, white
14	AGND	Reference potential for analog output	Coaxial screening
9	Laser on/off	Switching input Laser ON / OFF	red and blue
10	Zero	Switching input for reset	white and green
8	Switching output 1	Error or limit output	gray and pink
7	Switching output 2	Limit output	violet
3	Sync + <sup>1</sup>	Symmetrical synchron output (Master) or input (Slave)	blue
4	Sync - <sup>1</sup>		pink
1	Tx +	RS422 - Output (symmetric)	green
2	Tx -		brown
12	Rx +	RS422 - Input (symmetric)	gray
11	Rx -		yellow

### Plug connector:

ODU MINI-SNAP, 14-pin, series B, Dimension 2, Code 0, IP 68


More information on [www.odu.de](http://www.odu.de)

1) Used as trigger inputs in mode "Triggering", see Chap. 6.14.

### 15.3 Pin Assignment RS422 Connection

#### **i** IMPORTANT!

The system ground must be connected with the terminal ground (USB converter, pin 5) before connecting the Rx and Tx lines.



*Fig. 55 Principle setup*

Cross the lines for connections between sensor and PC.

ILD1700		Converter	
Signal	Color PC1700	Signal	Pin
RX-	yellow	TX-	1
RX+	gray	TX+	2
TX+	green	RX+	3
TX-	brown	RX-	4
GND (Pin 6)	black	ground	5

*Fig. 56 Pin assignment and wiring*

**i** Disconnect or connect the D-sub connection between RS422 and USB converter when the sensor is disconnected from power supply only.

## 15.4 Factory Setting

Name	Setting		
LED	Level 1	Level 2	Level 3
output	Current	Hold last value	Sync/Error
speed	2.5 kHz	Master Synch off	115.2 KBaud
avg	1 (3)	Moving average	Binary format (no ASCII)
zero	off	...	...

Master value: 0.5 x measurement range

Upper limit: 101 % FSO / Digital value: 16365

Upper hysteresis value: 100 % FSO / Digital value: 16207

Lower hysteresis value: 0 % FSO / Digital value: 161


Lower limit: -1 % FSO / Digital value: 0

Press the „function/enter“ key 5 seconds to activate the factory settings if the sensor is in measurement mode (the “state“ LED is illuminated).

## 15.5 Pin Assignment PC1700-x/x/USB/OE/IND

9-pin Sub-D	Pin	Assignment	Power supply unit  Analog output
	1	Tx -	
	2	Tx +	
	3	Rx +	
	4	Rx -	
5	GND		

2-pin cable	Color	Assignment	Sensor
	red	4 ... 20 mA or 0 ... 10 V	
	black	AGND	



PC

The PC1700-x/x/USB/OE/IND includes open leads for analog output signal and power supply unit for 90 ... 235 VAC. Length x = 3 or 10 m.

**15.6 Accessory**

PC1700-3	Power supply and output cable, 3 m long, cable carriers suitable; cable diameter 6.8 mm ± 0.2 mm		
PC1700-10	Power supply and output cable, 10 m long, cable carriers suitable; cable diameter 6.8 mm ± 0.2 mm		
PC1700-x/IF2008	Interface and supply cable		
PC1700-x/USB/IND	USB power supply and output cable, 3 m, 10 m or 20 m long, including power supply unit (90 ... 235 VAC)		
RS422/USB converter	Interface converter RS422 to USB (useable with cable 1700-x/USB/IND inclusive driver)		
PC1700-x/x/USB/BNC	Like PC1700-x/USB, with additional BNC connector for analog output		
PC1700-x/x/USB/OE/IND	Like PC1700-x/USB, with additional open leads for analog output		
PS2010	Power supply 24 V for mounting on DIN-rail (input 230 VAC, output 24 VDC/2.5 A)		
IF2008	The IF2008 interface card enables the synchronous capture of 4 digital sensor signals series optoNCDT1700 or others and 2 encoders. In combination with the IF2008E a total of 6 digital signals, 2 encoder signals, 2 analog signals and 8 I/O signals can be acquired synchronously.		
SGH size S, M	Without air purging (with inlet and exhaust for cooling)		
SGHF size S, M	With air purging for the protective window		
Assembly aid	Stock no.	Sensor	Aluminum device for easy mounting of a sensor in direct reflection.
20,0 °	2555059	ILD1700-2DR	
17,6 °	2555060	ILD1700-10DR	
11,5 °	2555061	ILD1700-20DR	



MICRO-EPSILON MESSTECHNIK GmbH & Co. KG  
Königbacher Str. 15 · 94496 Ortenburg / Germany  
Tel. +49 (0) 8542 / 168-0 · Fax +49 (0) 8542 / 168-90  
info@micro-epsilon.de · www.micro-epsilon.com

X9751139-D071045HDR  
© MICRO-EPSILON MESSTECHNIK

